

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/24/2019

Submitted Date:

10/30/2019

Document Number:

688800648**FIELD INSPECTION FORM**Loc ID 333116 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Heil, John		john.heil@state.co.us	
Shorty, Priscilla		pshorty@hilcorp.com	All SW Inspections
Walker, Mandi		mwalker@hilcorp.com	
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213801	WELL	PR	07/01/2019	GW	067-05064	ABEYTA 17-1	EI
295624	WELL	PR	09/13/2008	GW	067-09535	ABEYTA 17-2	EI
468925	SPILL OR RELEASE	AC	10/29/2019		-	Abeyta 17-1	EI

General Comment:

On October 24, 2019 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Hilcorp Energy Company Abeyta #17-1. For the most recent field inspection report of this facility, please refer to document #685303342. This site visit was in response to Spill/Release Point ID #468925.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Free standing signs near separators.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Posted on well head signs.		
Corrective Action:		Date:	

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Stock panel fencing and partial sound walls around pump jack.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Fencing around separators and meter shacks.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Steel pipe barricade fencing around well head.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	

Type: Ancillary equipment	# 2		
Comment:	Telemetry equipment.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 213801 Type: WELL API Number: 067-05064 Status: PR Insp. Status: EIFacility ID: 295624 Type: WELL API Number: 067-09535 Status: PR Insp. Status: EIFacility ID: 468925 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental**Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: 4

Comment: [For more information regarding this release, please refer to document #402220002.](#)Corrective Action: [Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.](#)

Date: 11/29/2019

Reportable: YES

GPS: Lat 37.014053

Long -107.529718

Proximity to Surface Water: _____

Depth to Ground Water: 12

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Secondary containment for lube oil container.
Compaction	Pass	Gravel	Pass			
Berms	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On October 24, 2019 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Hilcorp Energy Company Abeyta #17-1. For the most recent field inspection report of this facility, please refer to document #685303342. This site visit was in response to Spill/Release Point ID #468925. During this field inspection an area of damp soil was observed from the separator towards the well head for the #17-1. A puddle of water was observed within the damp area.	hughesjo	10/30/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402226424	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4976766
688800649	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4976765