

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/18/2019

Submitted Date:

10/30/2019

Document Number:

690900090

FIELD INSPECTION FORMLoc ID 324766 Inspector Name: FISCHER, ALEX On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10468

Name of Operator: THUNDER RIVER PRODUCTION LLC

Address: 4545 POST OAK PLACE DR #240

City: HOUSTON State: TX Zip: 77027

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

6 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Neidel, Kris		kris.neidel@state.co.us	
		dacockrell@thunder-river.com	
Waldron, Emily		emily.waldron@state.co.us	
		john.stevens@thunder-river.com	
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
299110	WELL	SI	10/01/2016	OW	057-06483	Fuqua 19-02-10-1H	EI

General Comment:

On October 18, 2019, COGCC Environmental Staff (Alex Fischer) conducted an environmental field inspection of Thunder River Production LLC's (Thunder River) Fuqua 18-15 Location (Location ID: 324766) API 057-10468 and REM 13906. Weather was partially sunny and temperatures about 33 degrees Fahrenheit. CAs from Inspection Doc # 689803087 have not been addressed. REM 6938 remains open for Spill ID 2222753 from a January 27, 2012 incident. Analytical results from a 2013 sampling event shows exceedance to Table 910-1 constituents.

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unmarked and uncapped flow lines.		
Corrective Action:	Comply with Rule 603.f . " For unused , unmarked flow line risers 24 hrs. to lock out tag out. 30 days to remove riser.	Date:	11/01/2019
Type	TRASH		
Comment:	Metal container in NW corner of Location with trash and debris. Stainless steel line near ECU and flare. Rags and trash on location.		
Corrective Action:	Comply with Rule 603.f .	Date:	11/06/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
Crude Oil	Separator	<= 1 bbl		
Comment:	Oil staining on ground surface near the separator.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a.			Date: 11/30/2019

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
Comment:						
Corrective Action:					Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

--	--	--	--

Environmental**Spills/Releases:**

Type of Spill: OIL

Estimated Spill Volume: _____

Comment: REM 6938 remains open for Spill ID 2222753 from a January 27, 2012 incident. Analytical results from a 2013 sampling event shows exceedance to Table 910-1 constituents.

Corrective Action: Provide a Supplemental Form 27 update regarding the spill and remediation. Contact area Environmental Protection Specialist (EPS) Kris Neidel at Kris.Neidel@state.co.us or 970-871-1963 within 2-weeks of this submittal (November 13, 2019) regarding this spill and remediation.

Date: 11/30/2019

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Waste Management:

Type Management Condition GPS (Lat) (Long)

Drums, Buckets,
Containers

Other

Inadequate

Comment: Unlabeled 55-gallon container, AST, and chemical container.

Corrective Action: Install sign/labels to comply with Rule 210.d.

Date: 11/30/2019

Spill/Remediation:

Comment: REM 6938 remains open for Spill ID 2222753 from a January 27, 2012 incident. Analytical results from a 2013 sampling event shows exceedance to Table 910-1 constituents

Corrective Action: Provide a Supplemental Form 27 update regarding the spill and remediation. Contact area Environmental Protection Specialist (EPS) Kris Neidel at Kris.Neidel@state.co.us or 970-871-1963 within 2-weeks of this submittal (November 13, 2019) regarding this spill and remediation.

Date: 11/30/2019

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

COGCC Comments

Comment	User	Date
Signage directing oil field traffic to the Location is under previous operators' name.	fischera	10/30/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402226675	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4976914
690900091	INSP Photo Fuqua 18-15 Location 324766 20191018	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4976910