

# Interim Reclamation and Stormwater Inspection

November 4, 2019

Operator: LONGS PEAK RESOURCES LLC- #10611

Location ID: 439459

Inspection Document #: 697500782

Weld County, CO

SESE Section 28 T12N R65W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

**Inspection Photos**  
**Location Name: Motu East /2821-8CH**  
**Location ID: 439459**



**Photo 1.** Photo taken from the entrance of location, facing East. Photo illustrates Operator has performed interim reclamation to reduce areas only needed for production operations per Rule 1003. Note: Appears straw mulch was crimped as an erosion control but has already blown off location which will not ensure the seeded soil is stabilized. COGCC staff would recommend re-installing erosion controls and using long-fiber weed-free mulch.



**Photo 2.** Photo taken from the eastern location, facing East. See comments under Photo 1.

Inspection Photos  
Location Name: Motu East /2821-8CH  
Location ID: 439459



**Photo 3.** Photo taken from the southeastern well pad, facing North. See comments under Photo 1.



**Photo 4.** Photo taken from the southeastern well pad, facing West. See comments under Photo 1.



Inspection Photos  
Location Name: Motu East /2821-8CH  
Location ID: 439459



**Photo 5.** Photo taken from the western well pad, facing West. Operator claims that the western cut slope was properly stabilized. This photo illustrates that the cut slope has not been properly stabilized, as it remains in the same condition. There is no indication that a BMP has been installed or implemented.