

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/06/2019

Submitted Date:

11/07/2019

Document Number:

694900751

**FIELD INSPECTION FORM**

Loc ID: 335542      Inspector Name: Ramsey, Scott      On-Site Inspection:       2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**  
 14 Number of Comments  
 3 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**  
 OGCC Operator Number: 10447  
 Name of Operator: URSA OPERATING COMPANY LLC  
 Address: 950 17TH STREET, SUITE 1900  
 City: DENVER      State: CO      Zip: 80202

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288407	WELL	PR	07/01/2019	GW	045-13227	VALLEY FARMS E5	PR
288408	WELL	PR	07/01/2019	GW	045-13226	VALLEY FARMS E6	PR
288411	WELL	PR	07/01/2019	GW	045-13223	VALLEY FARMS E9	PR
288412	WELL	PR	07/01/2019	GW	045-13222	VALLEY FARMS E10	PR
288413	WELL	PR	07/01/2019	GW	045-13221	VALLEY FARMS E11	PR

**General Comment:**

COGCC Inspection Report Summary  
 On Wednesday 11/6/19 at approximately 11:00 AM, I, Inspector Scott Ramsey, conducted a follow up inspection from inspection document # 689303028, 1/22/19 at URSA Valley farms E pad, at Location # 335542 in Garfield County, Colorado.  
 While there, I observed production operations. All C/A(s) have NOT been completed.  
 During this inspection the following possible compliance issues were observed:  
 Holes in secondary containment liner, see photos.  
 Condensate in drip pan next to tank burner that is in operation.  
 Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.  
 This is a summary of inspection report.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L		Date:
Overall Good: <input checked="" type="checkbox"/>			
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Corective actions required on FIR document #689303028, 1/22/19 were not made. Drip pan has condensate in it.		
Corrective Action:	Comply with Rule 603.f .		Date: 02/01/2019
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	livestock fence		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Bird Protectors	# 6		corrective date
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 3		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 8		
Comment:	Location is located in a wildlife RSO and SRA. Staff observed a hole in the burner assembly of the seperator unit on the west. Wildlife is not prevented from entering equipment.		

Corrective Action: <b>Prevent wildlife from entering equipment on location.</b>	Date: <b>11/15/2019</b>
---	-------------------------

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		

Comment: <b>centralized containment with 4 produced water tanks</b>	
Corrective Action:	Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Insufficient	Base Sufficient	Inadequate

Comment: <b>Corective actions required on FIR document #689303028, 1/22/19 were not made. Holes is containment secondary liner, see photos.</b>	
Corrective Action: <b>Repair or install berms or other secondary containment devices per Rule 906.d.(1).</b>	Date: <b>02/22/2019</b>

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	300 BBLs	STEEL AST		

Comment: <b>centralized containment with 1 condensate tank. 1 production water tank is heated and in operation.</b>	
Corrective Action:	Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:	
Corrective Action:	Date:

**Venting:**

Yes/No	NO
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	Ignitor/Combustor
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	<u>288407</u>	Type:	<u>WELL</u>	API Number:	<u>045-13227</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>288408</u>	Type:	<u>WELL</u>	API Number:	<u>045-13226</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>288411</u>	Type:	<u>WELL</u>	API Number:	<u>045-13223</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>288412</u>	Type:	<u>WELL</u>	API Number:	<u>045-13222</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>288413</u>	Type:	<u>WELL</u>	API Number:	<u>045-13221</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>producing</u>								
Corrective Action:					Date:				

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other						
Berms						

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694900752	694900751	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4983701">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4983701</a>