

Inspection Photos
Location Name: Jacobucci Jean 2
Location ID: 333139



Pic 1 lease road BMP failing



Pic 2 stained soil around exhaust and pumping unit motor