

Inspection Photo
Location Name: State 2-14
API: 05-099-06886



Erosion around leaning water tank