

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/04/2019

Submitted Date:

11/04/2019

Document Number:

687905752**FIELD INSPECTION FORM**Loc ID 441327 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**22 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	<a href="#">COGCC</a>
Inspections, All		SanJuanCOGCC@bp.com	<a href="#">All Inspections</a>
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	<a href="#">SW Inspection Reports</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
441326	WELL	PR	09/22/2015	LO	067-09927	Tubbs 32-6-9 B 4	PR
441328	WELL	PR	09/21/2015	LO	067-09928	Tubbs 32-6-9 A 2	PR

**General Comment:**[Site inspection and equipment inventory with photos at the end of this report.](#)

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Maintained gravel access road to location.		
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Signs posted at entrance to location.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Labels and placards posted on secondary containment ring and tank.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Contact information posted on signs		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	#B4 Pumpjack has been disconnected from wellhead. horsehead and long arms have been removed from gearbox and set along side of location. Sucker rod has been pulled and is sitting along side gearbox. Unused muffler laying on ground along side gearbox and unused disconnected engine oil tank sitting along side gearbox.		
Corrective Action:	Remove unused equipment or return to service per Rule 603.f.		Date: 12/04/2019
Type	TRASH		
Comment:	Broken off pieces of exhaust tubing laying on the ground at west end of #B4 pumpjack.		
Corrective Action:	Remove trash per Rule 603.f.		Date: 11/11/2019
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Barbed wire fence around location.		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Bradenhead	# 2		corrective date
Comment:	PVC bradenhead access on both wellheads.		
Corrective Action:			Date:
Type: Gas Meter Run	# 2		

Comment:		Inside duell separator building.		Date:	
Corrective Action:				Date:	
Type: Ancillary equipment	# 2				
Comment:		Wellheads with block valve assemblies installed.		Date:	
Corrective Action:				Date:	
Type: Flow Line	# 13				
Comment:		4-4" flowlines from wellheads to duell separator. 2-2" flowlines from separator blowdown to produced water tank. 2-1" flowlines from separator to pumpjack engines fuel gas. 2-2" flowlines from separator dump valves to produced water tank. 2-4" flowlines from separator merging to 1-4" flowline to offsite dogleg.		Date:	
Corrective Action:				Date:	
Type: Ancillary equipment	# 1				
Comment:		Sound panels around #A2 pumping unit.		Date:	
Corrective Action:				Date:	
Type: Prime Mover	# 2				
Comment:		#A2 natural gas powered engine exhaust has oil stained soil/gravel around edge of pumpjack skid and around muffler on ground.		Date:	
Corrective Action:		Clean-up stained soil/gravel per Rule 1002.f.(2)		Date:	11/11/2019
Type: Vertical Heated Separator	# 2				
Comment:		Duell unit.		Date:	
Corrective Action:				Date:	
Type: Pump Jack	# 2				
Comment:		#A2 pumping unit currently in service. #B4 pumping unit dismantled and not in use. See housekeeping section for unused equipment CA.		Date:	
Corrective Action:				Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		,
Comment:					
Corrective Action:		Date:			

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:		Date:		

**Venting:**

Yes/No	NO
--------	----

Comment:			
Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

**Inspected Facilities**Facility ID: 441326 Type: WELL API Number: 067-09927 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

Facility ID: 441328 Type: WELL API Number: 067-09928 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Ditches	Pass			
Gravel	Pass					
Compaction	Pass	Culverts	Pass			
Berms	Pass	Compaction	Pass			
Rip Rap	Pass					
				Material Handling And Spill Prevention	Pass	Spill prevention on engine oil tanks.
Gradient Terraces	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402230640	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4980185">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4980185</a>
687905753	Overview photo.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4980147">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4980147</a>
687905754	Disconnected (unused) pumpjack.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4980148">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4980148</a>
687905755	Unused equipment.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4980150">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4980150</a>
687905756	Unused equipment muffler, rod, oil tank.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4980151">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4980151</a>
687905757	Unused equipment.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4980153">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4980153</a>
687905758	Stained gravel/soil from muffler.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4980154">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4980154</a>
687905759	Stained gravel/soil from muffler.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4980155">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4980155</a>
687905760	Trash west end of pumpjack.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4980157">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4980157</a>