

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/05/2019

Submitted Date:

11/05/2019

Document Number:

687905773**FIELD INSPECTION FORM**Loc ID 428680 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 46685Name of Operator: KINDER MORGAN CO2 CO LPAddress: 1001 LOUISIANA ST SUITE 1000City: HOUSTON State: TX Zip: 77002**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hannigan, Michael	(970) 882-5532	CO2Source_Regulatory@kindermorgan.com	<a href="#">All Inspections</a>
Labowskie, Steve		steve.labowskie@state.co.us	<a href="#">COGCC</a>
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
428681	WELL	PR	07/23/2013	GW	083-06700	HE 6	PR

**General Comment:**[Site inspection and equipment inventory with photos at the end of this report.](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Maintained gravel access road.		
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign posted at entrance to location.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Company contact information is current. Missing local area emergency contact information or "911" on location sign. See photo.

Corrective Action: Update sign to include local emergency contact or "911" per Rule 210.

Date: 12/05/2019

Overall Good: ☐

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	Wellhead with block valve assembly.		
Corrective Action:		Date:	
Type: Flow Line	# 2		
Comment:	1-6" SS flowline from wellhead to valve stand at edge of location. 1-6" SS flowline from valve stand to offsite gathering system.		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	428681	Type:	WELL	API Number:	083-06700	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing.								
Corrective Action:				Date:					

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Ditches	Pass			
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402231960	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4981453">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4981453</a>
687905774	Missing emergency contact information.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4981443">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4981443</a>
687905775	Overview photo.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4981444">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4981444</a>