

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/05/2019

Submitted Date:

11/05/2019

Document Number:

687905776

**FIELD INSPECTION FORM**

Loc ID 313540 Inspector Name: Stewart, Joseph On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 46685  
 Name of Operator: KINDER MORGAN CO2 CO LP  
 Address: 1001 LOUISIANA ST SUITE 1000  
 City: HOUSTON State: TX Zip: 77002

**Findings:**

- 8 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Hannigan, Michael	(970) 882-5532	CO2Source_Regulatory@kindermorgan.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
224393	WELL	PR	03/06/2018	GW	083-06458	MCELMO DOME UNIT 35-38-19 HE #3	PR

**General Comment:**

[Site inspection and equipment inventory with photos at the end of this report.](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Maintained gravel road access.		
Corrective Action:		Date:	

Overall Good:

<b>Emergency Contact Number:</b>	
Comment:	Company contact information is current. Missing local area emergency contact information or "911" on location sign. See photo.
Corrective Action:	Update sign to include local emergency contact or "911" per Rule 210.
Date:	12/05/2019

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	Wellhead with block valve assembly installed.		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	1-3" SS flowline from wellhead changing to 1-6" SS flowline to offsite gathering system.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 3		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>	
Yes/No	NO
Comment:	
Corrective Action:	Date:

<b>Flaring:</b>	
Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 224393 Type: WELL API Number: 083-06458 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
		Gravel	Pass			
Gravel	Pass	Ditches	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402231961	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4981454">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4981454</a>
687905777	Missing emergency contact information.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4981445">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4981445</a>
687905779	Overview photo.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4981446">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4981446</a>