

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/21/2019

Submitted Date:

11/05/2019

Document Number:

688000338**FIELD INSPECTION FORM**Loc ID 312143 Inspector Name: YOUNG, ROB On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 52530Name of Operator: MAGPIE OPERATING INCAddress: 2707 SOUTH COUNTY RD 11City: LOVELAND State: CO Zip: 80537**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Warner, Ryan	720-233-0875	magpieoil@yahoo.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
111980	PIT	AC			-	WARNECKE LEASE	EI

General Comment:[Environmental inspection related to Rem #13484.](#)

Inspected Facilities									
Facility ID:	111980	Type:	PIT	API Number:	-	Status:	AC	Insp. Status:	EI

--

Environmental**Spill/Remediation:**

Comment: Former produced water pit has been partially backfilled. A siphon pipe requires removal and disposal. A former berm that partially divided the produced water pit is not three feet below grade. The surface of the berm requires sampling and analysis of pH, EC and SAR prior to being backfilled in place.

Corrective Action: Collect two surface soil samples from the berm north and south of the siphon pipe for pH, EC and SAR laboratory analysis for submittal on a supplemental Form 27

Date: 11/22/2019

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402231998	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4981486
688000339	Location photographs	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4981476