

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/05/2019

Submitted Date:

11/05/2019

Document Number:

699300498**FIELD INSPECTION FORM**Loc ID 305962 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|---------------|---------------------------------|
| , | | cogcc@kpk.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 284070 | WELL | SI | 10/01/2017 | OW | 123-23744 | COLCLASURE 42-21 | SI |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|----------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|--|--|-------------|
| Emergency Contact Number: | | | |
| Comment: | | | |
| Corrective Action: | | | Date: _____ |

| | | | |
|---------------------------|--|--|------------------|
| Good Housekeeping: | | | |
| Type | UNUSED EQUIPMENT | | |
| Comment: | PU has no Electric motor attached and no electric panel, transformers and meter box on location. | | |
| Corrective Action: | Comply with Rule 603.f | | Date: 12/05/2019 |

Overall Good: ☐

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

| | | | |
|--------------------|-----------|-------|--|
| Fencing/: | | | |
| Type | PUMP JACK | | |
| Comment: | Hog fence | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|----------------------------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Bradenhead | # 1 | | |
| Comment: | Appears to be plumbed to surface | | |
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|----|-------|--|
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected FacilitiesFacility ID: 284070 Type: WELL API Number: 123-23744 Status: SI Insp. Status: SI**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: TA. Well appears to be in the process of being put back into production. There is no motor on PU and no flow lines attached to WH.

Corrective Action: _____

Date: _____

COGCC Comments

| Comment | User | Date |
|--|--------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On Tuesday 11/05/2019 at approximately 1500 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at Colclasure #42-21 KP Kauffman, at API #05-123-23744 in Weld County Colorado. This is a follow up inspection per Doc. # 693500936</p> <p>While there, I observed a TA wellsite. Well appears to be in the process of being put back into production.</p> <p>During this inspection the following compliance issue was observed:</p> <p style="padding-left: 40px;">Unused equipment: Rule 603.f, PU appears to be reassembled although PU appears to not have a power source attached to it and no electric power source on location. Correction action date of 10-30-19.</p> <p style="padding-left: 40px;">See attached photos.</p> <p style="padding-left: 40px;">Location is wet in spots, weather is clear.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>Continuing education COGCC Inspection Report Summary.</p> | revasr | 11/05/2019 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 402232019 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4981593 |
| 699300499 | Location pics | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4981587 |