

Inspection Photos

API: 05-009-05182

Operator: TROJAN OIL & GAS COMPANY

Inspection Date: 11/12/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-009-05182 | Date: 11/12/2019

Inspection Photos



Photo 1. The location was leveled with the dozer.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-05182 | Date: 11/12/2019

Inspection Photos



Photo 2. The location was then decompacted from east to west.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-05182 | Date: 11/12/2019

Inspection Photos



Photo 3. Cross ripping was performed from south to north.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-05182 | Date: 11/12/2019

Inspection Photos



Photo 4. Soil was properly decompacted to 18 inches.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-05182 | Date: 11/12/2019

Inspection Photos



Photo 5. Facing west toward the location. The soils were cross ripped to 18 inches.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-05182 | Date: 11/12/2019

Inspection Photos



Photo 6. Facing west showing the area that was decompacted and the dozer ripper used for decompaction.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-05182 | Date: 11/12/2019