

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/08/2019

Submitted Date:

11/08/2019

Document Number:

699300545**FIELD INSPECTION FORM**Loc ID 336295 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections
Pesika, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241291	WELL	SI	06/01/2019	OW	123-09079	PERRIN-MAHONEY 2	SI

General Comment:

Location

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	Possible leak on flow line valve coming from WH.		
Corrective Action:	Rule 605.d: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition.	Date:	11/23/2019
Type	OTHER		
Comment:	Stained soil by flow line valve from WH		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e	Date:	11/23/2019

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	steel pipe		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	barb wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	electric panel		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	appears plumbed to surface		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	

Type: Pump Jack	#		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 241291 Type: WELL API Number: 123-09079 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Friday 11/8/2019 at approximately 1300 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at KP Kaufman:</p> <p style="text-align: center;">Perrin-Mahoney #2 at API #05-123-09079 in Weld County Colorado.</p> <p>While there, I observed a Shut in wellsite. Routine inspection. During this inspection the following compliance issue was observed: Rule 907.e: Stained soil by Flow line valve coming off WH. CA date 11/23/2019 see photos 3 & 4.</p> <p>Rule 605.d: COGCC Inspection Report Summary</p> <p>On Friday 11/8/2019 at approximately 1330 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at KP Kaufman:</p> <p style="text-align: center;">Perrin-Mahoney #2 at API #05-123-09079 in Weld County Colorado.</p> <p>While there, I observed a Shut in wellsite. Routine inspection. During this inspection the following compliance issue was observed: Rule 907.e: Stained soil by Flow line valve coming off WH. CA date 11/23/2019 see photos 3 & 4.</p> <p>Rule 605.d Mechanical issue: Possible leak on flow line valve coming from WH. CA date 11/23/2019 see photo 4.</p> <p>Location is dry, weather is clear.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>Continuing education COGCC Inspection Report Summary.</p> <p>This is a summary of inspection report.</p> <p>Location is dry, weather is clear.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>Continuing education COGCC Inspection Report Summary.</p> <p>This is a summary of inspection report.</p>	revasr	11/08/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402235092	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4984627
699300546	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4984626