

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/15/2019

Submitted Date:

11/15/2019

Document Number:

694900789

FIELD INSPECTION FORMLoc ID 417777 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10447

Name of Operator: URSA OPERATING COMPANY LLC

Address: 950 17TH STREET, SUITE 1900

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

21 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
417823	WELL	PR	01/17/2012	GW	045-19639	Frei A21	PR
417824	WELL	PR	01/17/2012	GW	045-19640	Frei A11	PR
417825	WELL	PR	01/24/2014	GW	045-19641	Frei A9	PR
417829	WELL	PR	10/28/2011	GW	045-19642	Frei A16	PR
419521	WELL	PR	06/11/2014	LO	045-19945	Frei A20	PR
419525	WELL	PR	09/24/2014	LO	045-19947	Frei A14	PR
419527	WELL	PR	07/21/2014	LO	045-19949	Frei A12	PR
419529	WELL	PR	06/15/2014	LO	045-19951	Frei A18	PR
419532	WELL	PR	06/24/2015	LO	045-19953	Frei A23	PR
419535	WELL	PR	06/08/2014	OW	045-19955	Frei A19	PR
419541	WELL	PR	06/22/2015	LO	045-19960	Frei A24	PR
419542	WELL	PR	09/24/2014	LO	045-19961	Frei A10	PR

General Comment:

COGCC Inspection Report Summary

On Friday 11/15/19 at approximately 11:30 AM, I, Inspector Scott Ramsey, conducted a routine inspection at URSA Frei A pad, at Location # 417777 in Garfield County, Colorado.

During this inspection the following possible compliance issues were observed:

- Debris behind alongside and inside tank battery
- Rat hole not maintained
- Wildlife escape boards on wells Frei A# and A4 need repositioned
- Dead man marker in pieces
- Staining in containment

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Emergency Contact Number:				
Comment:	911			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	OTHER			
Comment:	staining in containment			
Corrective Action:	remove staining			Date: 11/29/2019
Type	OTHER			
Comment:	old rat hole exposed and escape boards in two cellers see photos			
Corrective Action:	Maintain rat hole/ reposition wildlife escape boards			Date: 11/29/2019
Type	DEBRIS			
Comment:	debris behind, along side and inside of tank battery also broken deadman marker see photos			
Corrective Action:	remove debris			Date: 11/29/2019
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	livestock			
Corrective Action:				Date:
Equipment:				
Type: Emission Control Device	# 2			corrective date
Comment:				
Corrective Action:				Date:
Type: Plunger Lift	# 12			
Comment:				
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 16			
Comment:				
Corrective Action:				Date:

Type: Ancillary equipment	# 1	
Comment:	chemical tank	
Corrective Action:		Date:
Type: Bird Protectors	# 9	
Comment:		
Corrective Action:		Date:
Type: Deadman # & Marked	# 5	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	300 BBLs	STEEL AST		,
Comment:	centralized containment				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLs	STEEL AST		,
Comment:	1 tank is heated centralized containment				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	Ignitor/Combustor	
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	417823	Type:	WELL	API Number:	045-19639	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	417824	Type:	WELL	API Number:	045-19640	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	417825	Type:	WELL	API Number:	045-19641	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	417829	Type:	WELL	API Number:	045-19642	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	419521	Type:	WELL	API Number:	045-19945	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	419525	Type:	WELL	API Number:	045-19947	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	419527	Type:	WELL	API Number:	045-19949	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	419529	Type:	WELL	API Number:	045-19951	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			

Facility ID:	419532	Type:	WELL	API Number:	045-19953	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID:	419535	Type:	WELL	API Number:	045-19955	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID:	419541	Type:	WELL	API Number:	045-19960	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID:	419542	Type:	WELL	API Number:	045-19961	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				
Berms		Compaction				
Compaction		Ditches				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694900790	694900789	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4990336