

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/15/2019

Submitted Date:

11/15/2019

Document Number:

696300854**FIELD INSPECTION FORM**Loc ID 430123 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 10071Name of Operator: HIGHPOINT OPERATING CORPORATIONAddress: 555 17TH ST STE 3700City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------|---------------------------------|
| Kraich, Adam | | adam.kraich@state.co.us | |
| James, Brian | | bjames@hpres.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 430122 | WELL | TA | 09/09/2015 | OW | 123-36055 | Dutch Lake 24-22H | TA |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | BATTERY | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|--|-------|------------|
| Type | STORAGE OF SUPL | | |
| Comment: | Unmarked 1" and 2" Risers in north berm, see photo 3 | | |
| Corrective Action: | Comply with Rule 603.f . | Date: | 11/20/2019 |

Overall Good: ☐

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|----------------------|----------------------------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Bradenhead | # 1 | | |
| Comment: | Appears to be plumbed to Surface | | |
| Corrective Action: | | Date: | |
| Type: Other | # 1 | | |
| Comment: | TA'd Wellhead | | |
| Corrective Action: | | Date: | |
| Type: Gathering Line | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | |
|--------------------|---|----------|-----------|---------|--------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| PRODUCED WATER | 1 | 500 BBLS | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

Condition Adequate

| | |
|------------------|--|
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| | | | | | |
|--------------------|----------------------------------|---------------------|---------------------|-------------|----------------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| | | | | | |
| Comment: | Shares berm with Crude Oil Tanks | | | | |
| Corrective Action: | | | | Date: | |
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CRUDE OIL | 3 | 500 BBLS | STEEL AST | | 40.478730,104.314790 |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | |
|--------------------|-------|
| Yes/No | |
| Comment: | |
| Corrective Action: | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

| Inspected Facilities | | | | | | | | | |
|---|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 430122 | Type: | WELL | API Number: | 123-36055 | Status: | TA | Insp. Status: | TA |
| Idle Well | | | | | | | | | |
| Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned | | | | | | | | | |
| Reminder: _____ | | | | | | | | | |
| Comment: TA | | | | | | | | | |
| Corrective Action: _____ | | | | | | | | | |
| Date: _____ | | | | | | | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|--|--------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On Friday 11/08/2019 at approximately 12:45, I, Inspector Erica Petrie, conducted a Field Inspection at Highpoint Operating Corporation, Dutch Lake 24-22H, at Location ID #430123 in Weld County, Colorado.</p> <p>Unmarked 1" and 2" Risers inside North Berm, see photos 3. Comply with Rule 603.f.</p> <p>Corrective Action date 11.20.2019</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p> <p>Continuing Educational Inspections</p> | petrie | 11/15/2019 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 696300855 | Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4990393 |