

Inspection Photos
Operator: Hilcorp Energy
Location/API #: 067-08632
Date: 11-6-2019



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Revegetation is progressing here, largely with smooth brome.



Photo 3. View of the northern project area from the well pad entrance facing westward.



Photo 4. View of reference area west of the well pad, comprised of ponderosa pine forest with gambel oak understory.