

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/08/2019

Submitted Date:

11/12/2019

Document Number:

693801245**FIELD INSPECTION FORM**Loc ID 322448 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|--------------|-----------------------------|------------------------------------|
| Ried, Jordan | 970-563-4000 | maralextechjr@gmail.com | All Inspections |
| Labowskie, Steve | | steve.labowskie@state.co.us | |
| Graves, Jim | 970-858-8550 | mrinc20@qwestoffice.net | Operations Manager |
| Browning, Chuck | 970-433-4139 | chuck.browning@state.co.us | Field Inspector |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 210530 | WELL | TA | 02/01/2017 | GW | 045-06286 | BEAR GULCH 26-2 | TA |

General Comment:COGCC staff performed a routine field inspection on 11/8/2019.
Issues were found requiring corrective action. CA(s) from previous inspection not completed.

Location

| | | | |
|--------------------|---------|-------|--|
| Lease Road: | | | |
| Type | Main | | |
| comment: | BLM 265 | | |
| Corrective Action | | Date: | |

Overall Good: ☒

| | | | |
|----------------------|----------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: 970-858-8550 or 911

Corrective Action:

Date: _____

Overall Good: ☒

| | | | | | |
|----------------|------|--------|--|--|--|
| Spills: | | | | | |
| Type | Area | Volume | | | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|------------------|-------|--|
| Fencing/: | | | |
| Type | PIT | | |
| Comment: | Hogwire & T-post | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------------|-----|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Gas Meter Run | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Deadman # & Marked | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Dehydrator | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|------|--|--|
| Type | | |
|------|--|--|

| | | | |
|--------------------|--|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected FacilitiesFacility ID: 210530 Type: WELL API Number: 045-06286 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: Last MIT 8/10/2015.

Well was found in state of Temporary Abandonment. TA status has not been approved via Form 4. Ongoing reporting via Form 7 has not been conducted

Corrective Action: Submit for Form 4 to request approval for TA status . Submit Form 7s and bring reporting up to date.

Date: 11/29/2019

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | Compaction | Pass | | | |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: BlowdownLined: NO

Pit ID:

Lat: 39.598931Long: -108.686848Reference Point: SEOther: Length: 16Width: 16**Lining:**

Liner Type:

Liner Condition:

Comment: Corrective Action: Date: **Fencing:**Fencing Type: LivestockFencing Condition: AdequateComment: Corrective Action: Date: **Netting:**

Netting Type:

Netting Condition:

Comment: Corrective Action: Date:

Anchor Trench Present:

Oil Accumulation: NO

2+ feet Freeboard:

Comment: Corrective Action: Date: Type: BlowdownLined: NO

Pit ID:

Lat: 39.598830Long: -108.687009Reference Point: SEOther: Length: 22Width: 18**Lining:**

Liner Type:

Liner Condition:

Comment: Corrective Action: Date: **Fencing:**Fencing Type: LivestockFencing Condition: AdequateComment: Corrective Action: Date: **Netting:**

Netting Type:

Netting Condition:

Comment:

Inspector Name: BROWNING, CHUCK

| | | |
|------------------------|-----------------------------|--------------------|
| Corrective Action | | Date: |
| Anchor Trench Present: | Oil Accumulation: <u>NO</u> | 2+ feet Freeboard: |
| Comment: | | |
| Corrective Action | | Date: |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-----------------------------|---|
| 402237677 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4986735 |
| 693801252 | Inspection photos 11/8/2019 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4986731 |