

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/18/2019

Submitted Date:

11/20/2019

Document Number:

693200451

### FIELD INSPECTION FORM

Loc ID 335023 Inspector Name: Murray, Richard On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10456  
Name of Operator: CAERUS PICEANCE LLC  
Address: 1001 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	Engineering Integrity Supervisor
		rcowden@caerusoilandgs.com	
Arauza, Steven		steven.arauza@state.co.us	West Environmental Protection Specialist
		COGCC.inspections@caerusoilandgas.com	All Piceance inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
469248	SPILL OR RELEASE	AC	11/15/2019		-	17F Flowline Spill	AC

**General Comment:**

Engineering Integrity Inspection performed on November 18, 2019. In response to initial form 19 spill report Doc # 402239250

**Inspected Facilities**

Facility ID: 469248 Type: SPILL OR API Number: - Status: AC Insp. Status: AC

**Flowline**

#1	Type: Dump Line	of Lines
----	-----------------	----------

Flowline Description

Flowline Type: Dump Line Size: \_\_\_\_\_ Material: Carbon Steel  
 Variance: No Age: 5-10 Yrs Contents: Multiphase

Integrity Summary

Failures: Other Spills: Yes Repairs Made: No  
 Coatings: \_\_\_\_\_ H2S: No Cathodic Protection: No

Pressure Testing

Witnessed: \_\_\_\_\_ Test Result: \_\_\_\_\_ Charted: \_\_\_\_\_

COGCC Rules(check all that apply)

1101. Installation and Reclamation  1102. Operations, Maintenance, and Repair  1103. Abandonment

Comment: Wells are secure, locked out and tag out  
Contact Western integrity Inspector when Flowline is exposed and ready to cut out and when pressure test is performed before returning to service.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693200453	Phot log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4993071">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4993071</a>