

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/19/2019

Submitted Date:

11/20/2019

Document Number:

693200454

FIELD INSPECTION FORMLoc ID 312714 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		rcowden@caerusoilandgas.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	Engineering Integrity Supervisor
Arauza, Steven		steven.arauza@state.co.us	West Environmental Protection Specialist
		COGCC.inspections@caerusoilandgas.com	All Piceance inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278836	WELL	PR	07/05/2016	GW	077-08925	ORCHARD UNIT 16-16 (P16OU)	SI
413043	WELL	PR	11/01/2011	OW	077-10071	ORCHARD UNIT 16-16H2 (P16OU)	PR
413044	WELL	PR	02/14/2012	GW	077-10072	ORCHARD UNIT 16-16H (P16OU)	PR

General Comment:

Engineering Integrity Inspection performed on November 19, 2019. In response to initial form 19 spill report Doc # 402241656

Inspected FacilitiesFacility ID: 278836 Type: WELL API Number: 077-08925 Status: PR Insp. Status: SIFacility ID: 413043 Type: WELL API Number: 077-10071 Status: PR Insp. Status: PRFacility ID: 413044 Type: WELL API Number: 077-10072 Status: PR Insp. Status: PR**Flowline**

#1 Type: Dump Line 1 of Lines

Flowline DescriptionFlowline Type: Dump Line

Size:

Material: Carbon SteelVariance: No

Age:

Contents: MultiphaseIntegrity Summary

Failures:

Spills: YesRepairs Made: No

Coatings:

H2S: No

Cathodic Protection:

Pressure Testing

Witnessed:

Test Result:

Charted:

COGCC Rules(check all that apply)☐ 1101. Installation and Reclamation☒ 1102. Operations, Maintenance, and Repair☐ 1103. AbandonmentComment: Wells are secure, locked out and tag outContact Western integrity Inspector when Flowline is exposed and ready to cut out and when pressure test is performed before returning to service.

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693200455	photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4993178