

Inspection Photos

11/06/2019

Operator: MARALEX RESOURCES INC - 53255

Location ID: 312599

Mesa County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: MARALEX RESOURCES INC - 53255
Location ID: 312599



Photo 1: Photo taken from the access road, facing west. Photo provides overview of the location.



Photo 2: Photo taken from the culvert adjacent to the access road. Photo shows stormwater erosion degradation. 6 foot measuring stick for reference area.

Inspection Photos
Operator Name: MARALEX RESOURCES INC - 53255
Location ID: 312599



Photo 3: Photo taken from the location, facing west. Photo shows stormwater erosion degradation occurring throughout location. Operator has failed to conduct ongoing stormwater monitoring and management, resulting in reclamation failure of the location.



Photo 4: Continued from photo 3. 6 foot measuring stick for reference.

Inspection Photos
Operator Name: MARALEX RESOURCES INC - 53255
Location ID: 312599



Photo 5: Photo taken from the west end of the location, facing south. Photos 5-7 provide an overview of the location from south, east, to northeast. Photo shows erosion degradation on location.



Photo 6: See comments under photo 5.

Inspection Photos
Operator Name: MARALEX RESOURCES INC - 53255
Location ID: 312599



Photo 7: See comments under photo 5.



Photo 8: Photo taken from the location, facing east. Photo shows erosion degradation on location.

Inspection Photos

Operator Name: MARALEX RESOURCES INC - 53255

Location ID: 312599



Photo 9: Photo taken from the location. Photo shows what appears to be a rock-check installed in the low areas of the location. BMP does not appear to have been constructed in accordance with good engineering practices and is not in proper functioning condition.



Photo 10: Continued from photo 9.

Inspection Photos
Operator Name: MARALEX RESOURCES INC - 53255
Location ID: 312599



Photo 11: Photo of culvert under access road and erosion degradation.



Photo 12: Photo taken down-slope of the culvert. Photo shows erosion degradation due to stormwater runoff from the location.