

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

11/14/2019

Submitted Date:

11/14/2019

Document Number:

699300568

FIELD INSPECTION FORM
 Loc ID 317489 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10071Name of Operator: HIGHPOINT OPERATING CORPORATIONAddress: 555 17TH ST STE 3700City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**13 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------|-------|----------------------------------|-----------------|
| Pesika, Conor | | conor.pesicka@state.co.us | |
| , | | dnr_cogccengineering@state.co.us | |
| , | | dnr_cogccenforcement@state.co.us | |
| , | | cogcc@kpk.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 238228 | WELL | SI | 07/01/2017 | GW | 123-05061 | SHOE 1 | SI |

General Comment:

| Location | | | |
|--|--|--------|-----------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Weeds overgrown on access Rd. | | |
| Corrective Action: | Comply with Rule 603.f | Date: | 11/21/2019 |
| Overall Good: <input type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | WH sign has old operator information. Form 10 was submitted on 5/1/2019 and is in process. | | |
| Corrective Action: | Comply with Rule 210.b | Date: | 12/14/2019 |
| Type | BATTERY | | |
| Comment: | TB sign has old operator information. Form 10 was submitted on 5/1/2019 and is in process. | | |
| Corrective Action: | Comply with Rule 210.b | Date: | 12/14/2019 |
| Emergency Contact Number: | | | |
| Comment: | | | |
| Corrective Action: | | | Date: _____ |
| Good Housekeeping: | | | |
| Type | DEBRIS | | |
| Comment: | Weeds overgrown on entire location | | |
| Corrective Action: | Comply with Rule 603.f | Date: | 11/21/2019 |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Steel pipe | | |
| Corrective Action: | | Date: | |
| Type | LOCATION | | |
| Comment: | Barbwire | | |
| Corrective Action: | | Date: | |
| Equipment: | | | |
| Type: Bradenhead | # 1 | | corrective date |
| Comment: | Appears to be plumbed to surface | | |

| | | | |
|-----------------------------------|------------|-------|--|
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 2 | | |
| Comment: | Automation | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CRUDE OIL | 1 | 300 BBLs | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|------------|
| Condition | Inadequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | | |
|--------------------|--|-------|------------|
| Yes/No | YES | | |
| Comment: | Well appears to be venting along threads | | |
| Corrective Action: | Comply with Rule 912.b Rule 605.d. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition. | Date: | 11/15/2019 |

Flaring:

| | |
|----------|--|
| Type | |
| Comment: | |

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
|--------------------|--|-------|--|

Inspected FacilitiesFacility ID: 238228 Type: WELL API Number: 123-05061 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Well appears to be SI and is venting from around threads of WH see attached video.

Corrective Action: _____

Date: _____

COGCC Comments

Comment

User

Date

COGCC Inspection Report Summary

On Thursday 11/14/2019 at approximately 1200 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at the Shoe #1KP Kauffman, at API # 05-123-05061 in Weld County Colorado.

While there, I observed SI well and Tank battery.

During this inspection the following possible compliance issues were observed:

Rule 603.f Housekeeping: Dead weeds on access road, and throughout well site location.

CA date 9/13/2019 see attaches photos #1, 2, 4, 5 and 7.

605.d Mechanical conditions and 912.b: Wellhead appears to be venting around the threads to atmosphere. Securely fasten all valves, pipes and fittings to ensure good mechanical conditions inspect at regular intervals and maintain. 30 days unless leak is found then 24 hrs. To repair or isolate the leak. CA date 11/15/2019 See attached video.

WH sign and TB sign still show Highpoint Resources and their emergency number. The form 10 was submitted on 5/1/2019 and is in process KP Kauffman should replace signs immediately so proper information is at wellsite See attached photo #3 and 6.

Location is dry, weather is cloudy.

I called KP Kauffman emergency number and spoke with Janette at approx. 1215 hrs she took down the information and said she would relay it to the on call representative and have him give me a call to go over what I observed. At approximately 1300 hrs I spoke with Chris Ellis with KP Kauffman I explained that the WH is venting gas around the threads and needed to be tightened up or WH replaced, he said that it sounded like it might be the packing and he would get it tightened up.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.

Continuing education COGCC Inspection Report Summary.

This is a summary of inspection report.

revasr

11/14/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 402240240 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4989325 |
| 699300569 | location pics | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4989319 |
| 699300571 | WH video | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4989320 |