

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/20/2019

Submitted Date:

11/22/2019

Document Number:

696101590**FIELD INSPECTION FORM**Loc ID 310064 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 8960Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANYAddress: 410 17TH STREET SUITE #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:18 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		EHSRC@bonanzacrk.com	All Inspections
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295871	WELL	TA	04/01/2019	OW	123-25826	NORTH PLATTE 13-24	TA

General Comment:

This is a WELL inspection.

Well(s): 1: Temporarily Abandoned | TA.

Battery: Inactive | Shut-down.

Centralized Battery serves 4 Location IDs (310063, 310064, 310068, 413628).

(Well(s): 4: Temporarily Abandoned | TA).

Refer to Field Inspection Report doc. #696101588 and/or Location ID #310063
for Battery / Facility, Equipment info.

Location				
Lease Road:				
Type	Access			
comment:	Adequate			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Type				
Comment:	Refer to Field Inspection Report doc. #696101588 and/or Location ID #310063 for Battery / Facility, Equipment info.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No _____				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type				
Comment:	Refer to Field Inspection Report doc. #696101588 and/or Location ID #310063 for Battery / Facility, Equipment info.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Iron panel.			
Corrective Action:				Date:
Equipment:				
Type: Bradenhead	# 1			corrective date
Comment:	Appears plumbed to surface.			
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 0			
Comment:	Refer to Field Inspection Report doc. #696101588 and/or Location ID #310063 for Battery / Facility, Equipment info.			
Corrective Action:				Date:
Type: Other	# 1			

Comment: Wellhead: w/ Master & casing valves.			
Corrective Action:		Date:	
Type: Ancillary equipment	# 0		
Comment: Refer to Field Inspection Report doc. #696101588 and/or Location ID #310063 for Battery / Facility, Equipment info.			
Corrective Action:		Date:	
Type: Emission Control Device	# 0		
Comment: Refer to Field Inspection Report doc. #696101588 and/or Location ID #310063 for Battery / Facility, Equipment info.			
Corrective Action:		Date:	
Type: Plunger Lift	# 0		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 0		
Comment: Refer to Field Inspection Report doc. #696101588 and/or Location ID #310063 for Battery / Facility, Equipment info.			
Corrective Action:		Date:	
Type: Gas Meter Run	# 0		
Comment: Refer to Field Inspection Report doc. #696101588 and/or Location ID #310063 for Battery / Facility, Equipment info.			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment: Centralized Battery serves 4 Location IDs (310063, 310064, 310068, 413628). (Well(s): 4: Temporarily Abandoned TA). Refer to Field Inspection Report doc. #696101588 and/or Location ID #310063 for Battery / Facility, Equipment info.					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				,

Comment:	Refer to Field Inspection Report doc. #696101588 and/or Location ID #310063 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	0				,

Comment:	Refer to Field Inspection Report doc. #696101588 and/or Location ID #310063 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	295871	Type:	WELL	API Number:	123-25826	Status:	TA	Insp. Status:	TA
Idle Well									
Purpose:		<input type="checkbox"/> Shut In		<input checked="" type="checkbox"/> Temporarily Abandoned		Reminder: EQUIPMENT PRESENT/DISCONNECTED			
Comment:		<div>Temporarily Abandoned TA. Observed well disconnected from flowline. Form 4 doc. #401677227 indicates TA: 07/21/2014. Approved. Form 21 Doc# 401107214 MIT done: 05/24/2016. Approved.</div>							
Corrective Action:							Date:		

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On WED 11/20/2019 at approximately 12:55 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC Location Name: North Platte /13-24 Pad Location ID: 310064 Well Name: North Platte 13-24 API: 05-123-25826 Location County: Weld County, Colorado Weather: Overcast & Dry.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 4 Location IDs (310063, 310064, 310068, 413628). (Well(s): 4: Temporarily Abandoned TA).</p> <p>Refer to Field Inspection Report doc. #696101588 and/or Location ID #310063 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	11/22/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101591	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4995611