

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/20/2019

Submitted Date:

11/22/2019

Document Number:

696101592

FIELD INSPECTION FORM

Loc ID 310068 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 8960
 Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY
 Address: 410 17TH STREET SUITE #1400
 City: DENVER State: CO Zip: 80202

Findings:

- 13 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		EHSRC@bonanzacrk.com	All Inspections
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295875	WELL	TA	09/12/2014	OW	123-25830	NORTH PLATTE 12-24	TA

General Comment:

This is a WELL inspection.
 Well(s): 1: Temporarily Abandoned | TA.
 Battery: Inactive | Shut-down.

Centralized Battery serves 4 Location IDs (310063, 310064, 310068, 413628).
 (Well(s): 4: Temporarily Abandoned | TA).

Refer to Field Inspection Report doc. #696101588 and/or Location ID #310063 for Battery / Facility, Equipment info.

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign at access road to wellsite. Well not visible from sign. Consider posting an additional sign at wellsite similar to what is at other Bonanza Creek wells. See photos #1, 2.		
Corrective Action:			Date:
Type			
Comment:	Refer to Field Inspection Report doc. #696101588 and/or Location ID #310063 for Battery / Facility, Equipment info.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:			Date:
Type			
Comment:	Refer to Field Inspection Report doc. #696101588 and/or Location ID #310063 for Battery / Facility, Equipment info.		
Corrective Action:			Date:
Equipment:			
Type:		#	corrective date
Comment:	Refer to Field Inspection Report doc. #696101588 and/or Location ID #310063 for Battery / Facility, Equipment info.		
Corrective Action:			Date:
Type: Other		# 1	
Comment:	Wellhead: w/ Master & casing valves.		
Corrective Action:			Date:
Type: Bradenhead		# 1	

Comment:	Appears plumbed to surface.	Date:	
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.378899,-104.391792
Comment:	Centralized Battery serves 4 Location IDs (310063, 310064, 310068, 413628). (Well(s): 4: Temporarily Abandoned TA). Refer to Field Inspection Report doc. #696101588 and/or Location ID #310063 for Battery / Facility, Equipment info.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 295875 Type: WELL API Number: 123-25830 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA. Observed well disconnected from flowline.
Form 4 doc. #402066840 indicates TA: 08/19/2014. Approved.
Form 21 Doc# 401107211 MIT done: 05/24/2016. Approved.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On WED 11/20/2019 at approximately 13:09 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC Location Name: North Platte /12-24 Pad Location ID: 310068 Well Name: North Platte 12-24 API: 05-123-25830 Location County: Weld County, Colorado Weather: Overcast & Dry.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 4 Location IDs (310063, 310064, 310068, 413628). (Well(s): 4: Temporarily Abandoned TA).</p> <p>Refer to Field Inspection Report doc. #696101588 and/or Location ID #310063 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	11/22/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101593	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4995613