

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/20/2019

Submitted Date:

11/22/2019

Document Number:

696101594

**FIELD INSPECTION FORM**

Loc ID 413628 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 8960  
 Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY  
 Address: 410 17TH STREET SUITE #1400  
 City: DENVER State: CO Zip: 80202

**Findings:**

12 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		dnr_cogccengineering@state.co.us	
		EHSRC@bonanzacrk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412514	WELL	TA	11/01/2014	GW	123-30508	NORTH PLATTE 24C	TA

**General Comment:**

This is a WELL inspection.  
 Well(s): 1: Temporarily Abandoned | TA.  
 Battery: Inactive | Shut-down.  
  
 Centralized Battery serves 4 Location IDs (310063, 310064, 310068, 413628).  
 (Well(s): 4: Temporarily Abandoned | TA).  
  
 Refer to Field Inspection Report doc. #696101588 and/or Location ID #310063 for Battery / Facility, Equipment info.

<b>Location</b>			
<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type			
Comment:	Refer to Field Inspection Report doc. #696101588 and/or Location ID #310063 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	
<b>Emergency Contact Number:</b>			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	
Type			
Comment:	Refer to Field Inspection Report doc. #696101588 and/or Location ID #310063 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	
<b>Equipment:</b>			
Type: Plunger Lift	# 0		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Wellhead: w/ Master & casing valves.		
Corrective Action:		Date:	

Type:	#	
Comment:	Refer to Field Inspection Report doc. #696101588 and/or Location ID #310063 for Battery / Facility, Equipment info.	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.378899,-104.391792
Comment:	Centralized Battery serves 4 Location IDs (310063, 310064, 310068, 413628). (Well(s): 4: Temporarily Abandoned   TA). Refer to Field Inspection Report doc. #696101588 and/or Location ID #310063 for Battery / Facility, Equipment info.				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 412514 Type: WELL API Number: 123-30508 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA. Observed well disconnected from flowline.  
Form 4 doc. #402066840 indicates TA: 08/15/2014. Approved.  
Form 21 Doc# 401107185 MIT done: 05/24/2016. Approved.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On WED 11/20/2019 at approximately 12:46 hrs. I, Bret Evins, conducted an on-site inspection at:                      Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC                      Location Name: NORTH PLATTE /24C                      Location ID: 413628                      Well Name: North Platte 24C                      API: 05-123-30508                      Location County: Weld County, Colorado                      Weather: Overcast &amp; Dry.</p> <p>While there, I observed:                      Well(s): 1: Temporarily Abandoned   TA.                      Battery: Inactive   Shut-down.</p> <p>Centralized Battery serves 4 Location IDs (310063, 310064, 310068, 413628).                      (Well(s): 4: Temporarily Abandoned   TA).</p> <p>Refer to Field Inspection Report doc. #696101588 and/or Location ID #310063 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	11/22/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101595	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4995614">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4995614</a>