

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/20/2019

Submitted Date:

11/22/2019

Document Number:

696101596

**FIELD INSPECTION FORM**

Loc ID 310067 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 8960  
 Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY  
 Address: 410 17TH STREET SUITE #1400  
 City: DENVER State: CO Zip: 80202

**Findings:**

- 17 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		EHSRC@bonanzacrk.com	<a href="#">All Inspections</a>
,		dnr_cogccengineering@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295874	WELL	TA	10/16/2014	OW	123-25829	NORTH PLATTE 23-24	TA

**General Comment:**

This is a WELL & BATTERY inspection.  
 Well(s): 1: Temporarily Abandoned | TA.  
 Battery: Inactive | Shut-down.  
  
 Centralized Battery serves 2 Location IDs (310067, 310065).  
 (Well(s): 2: Temporarily Abandoned | TA).

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Sign at access road to wellsite. Well is visible from sign. Consider posting an additional sign at wellsite similar to what is at other Bonanza Creek wells. See photos #1, 2.		
Corrective Action:			Date:

Emergency Contact Number:

Comment:			
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Barbed wire. Surrounded by earth berms.		
Corrective Action:			Date:
Type	IGNITOR/COMBUSTOR		
Comment:	Barbed wire.		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Barbed wire.		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Other	# 1		
Comment:	Wellhead: w/ Master & casing valves.		
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:	Controls crude oil tanks VOCs. Pilots: OFF   Shut-down.		
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 0		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	ECD scrubber.		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		
Comment:	Centralized Battery serves 2 Location IDs (310067, 310065).				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				

Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.382849,-104.386612
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Shares berms w/ produced H2O vault.				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	CONCRETE SUMP/VAULT		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	60 Bbls.
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Shares berms w/ crude oil tank tank.				
Corrective Action:				Date:

**Venting:**

Yes/No	NO
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 295874 Type: WELL API Number: 123-25829 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA. Observed well disconnected from flowline.  
Form 4 doc. #401677247 indicates TA: 07/22/2014. Approved.  
Form 21 Doc# 401108004 MIT done: 05/24/2016. Approved.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On WED 11/20/2019 at approximately 13:37 hrs. I, Bret Evins, conducted an on-site inspection at:                      Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC                      Location Name: North Platte /23-24                      Location ID: 310067                      Well Name: North Platte 23-24                      API: 05-123-25829                      Location County: Weld County, Colorado                      Weather: Overcast &amp; Dry.</p> <p>While there, I observed:                      Well(s): 1: Temporarily Abandoned   TA.                      Battery: Inactive   Shut-down.</p> <p>Centralized Battery serves 2 Location IDs (310067, 310065).                      (Well(s): 2: Temporarily Abandoned   TA).</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	11/22/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101597	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4995650">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4995650</a>