

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/20/2019

Submitted Date:

11/22/2019

Document Number:

696101600**FIELD INSPECTION FORM**Loc ID 413629 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 8960Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANYAddress: 410 17TH STREET SUITE #1400City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**18 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
,		EHSRC@bonanzacrk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412525	WELL	TA	10/16/2014	GW	123-30515	NORTH PLATTE 24A	TA

General Comment:

This is a WELL & BATTERY inspection.
 Well(s): 1: Temporarily Abandoned | TA.
 Battery: Inactive | Shut-down.

Centralized Battery serves 4 Location IDs (413629, 310062, 310066, 310069).
 (Well(s): 4: Temporarily Abandoned | TA).

Location				
Lease Road:				
Type	Access			
comment:	Adequate			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Sign at access road to wellsite. Well NOT visible from sign. Consider posting an additional sign at wellsite similar to what is at other Bonanza Creek wells. See photos #1, 2.			
Corrective Action:				Date:
Type	BATTERY			
Comment:				
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:	Contents & Capacity NOT posted at what appears to be produced H2O tank. Refer to Rule 210.d. See photo #4.			
Corrective Action:	Post Contents & Capacity at what appears to be produced H2O tank. Comply w/ Rule 210.d. See photo #4.			Date: 01/21/2020
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No _____				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	SEPARATOR			
Comment:	Barbed wire. Surrounded by earth berms.			
Corrective Action:				Date:
Type	TANK BATTERY			
Comment:	Barbed wire.			
Corrective Action:				Date:
Type	IGNITOR/COMBUSTOR			
Comment:	Barbed wire.			
Corrective Action:				Date:
Type	WELLHEAD			

Comment: Iron panel.			
Corrective Action:		Date:	

Equipment:

Type: Ancillary equipment	# 1		corrective date
Comment: ECD scrubber.			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment: Appears plumbed to surface.			
Corrective Action:		Date:	
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment: Wellhead: w/ Master & casing valves.			
Corrective Action:		Date:	
Type: Plunger Lift	# 0		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment: Controls crude oil tanks VOCs. Pilots: OFF Shut-down.			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment: Centralized Battery serves 4 Location IDs (413629, 310062, 310066, 310069).					
Corrective Action:		Date:			

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,
Comment:					
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	Unknown
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment: Shares berms w/ crude oil tank tanks.				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	300 BBLs	STEEL AST		40.389129,-104.388301
Comment:					
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment: Shares berms w/ produced H2O tank.				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	412525	Type:	WELL	API Number:	123-30515	Status:	TA	Insp. Status:	TA
Idle Well									
Purpose:		<input type="checkbox"/> Shut In		<input checked="" type="checkbox"/> Temporarily Abandoned		Reminder: EQUIPMENT PRESENT/DISCONNECTED			
Comment:		<div>Temporarily Abandoned TA. Observed well disconnected from flowline. Form 4 doc. #402066871 indicates TA: 08/08/2014. Approved. Form 21 Doc# 401107902 MIT done: 05/24/2016. Approved.</div>							
Corrective Action:							Date:		

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On WED 11/20/2019 at approximately 14:21 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC Location Name: NORTH PLATTE /24A Location ID: 413629 Well Name: North Platte 24A API: 05-123-30515 Location County: Weld County, Colorado Weather: Overcast & Dry.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 4 Location IDs (413629, 310062, 310066, 310069). (Well(s): 4: Temporarily Abandoned TA).</p> <p>During this inspection the following possible compliance issues were observed: 1.) Contents & Capacity NOT posted at what appears to be produced H2O tank. Refer to Rule 210.d. Post Contents & Capacity at what appears to be produced H2O tank. Comply w/ Rule 210.d. Corrective Action Date: 01/21/2020 See photo #4.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	evinsb	11/22/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101601	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4995699