

Inspection Photos  
Location Name: A27  
Spill/Release ID: 468839  
Inspection Date: October 21, 31, 2019




Photo #1 – View of the Water Collection / Treatment and Condensate Recovery System display. The vault inlet and outlet were flowing at approximately 49 GPM.



Photo #2 – View of the ruptured poly pipe looking south.





**Inspection Photos**  
**Location Name: A27**  
**Spill/Release ID: 468839**  
**Inspection Date: October 21, 31, 2019**



**Photo #3 - View of the ruptured poly pipe looking south.**



**Photo #4 – View of the ruptured poly pipe.**





**Inspection Photos**  
**Location Name: A27**  
**Spill/Release ID: 468839**  
**Inspection Date: October 21, 31, 2019**



**Photo #5 – View of the ruptured poly pipe.**



**Photo #6 – Hydrocarbon seep north of the weir and south of the Water Collection Vault.**





**Inspection Photos**  
**Location Name: A27**  
**Spill/Release ID: 468839**  
**Inspection Date: October 21, 31, 2019**



**Photo # – Hydrocarbon sheen noted on surface water north of the weir and south of the Water Collection Vault.**



**Photo # – Hydrocarbon Seep north of the weir and south of the Water Collection Vault.**





**Inspection Photos**  
**Location Name: A27**  
**Spill/Release ID: 468839**  
**Inspection Date: October 21, 31, 2019**



**Photo #7 - View of the repaired poly pipe with additional support.**



**Photo #8 – View of the repaired section and the kink in the poly pipe (Red circle).**



**Inspection Photos**  
**Location Name: A27**  
**Spill/Release ID: 468839**  
**Inspection Date: October 21, 31, 2019**



**Photo #9 – View of the kink in the poly pipe.**



**Photo #10 – View of the kink in the poly pipe looking north.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: A27  
Spill/Release ID: 468839  
Inspection Date: October 21, 31, 2019



**Photo #11 – View of the pump generator secondary containment in disrepair.**



**Photo # - View of the pump generator secondary containment in disrepair.**



**Inspection Photos**  
**Location Name: A27**  
**Spill/Release ID: 468839**  
**Inspection Date: October 21, 31, 2019**



**Photo #13 – View of the stained soil with a detectable hydrocarbon odor located north of the Water Collection Vault.**



**Photo #14 – View of the Operator's truck blocking access to the northern section of the location.**

