

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/21/2019

Submitted Date:

11/22/2019

Document Number:

699700048

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Heil, John On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10442
 Name of Operator: HUNTER RIDGE ENERGY SERVICES LLC
 Address: 370 17TH STREET #1700
 City: DENVER State: CO Zip: 80202

Findings:

- 5 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Henry, Jen		Jennifer.Henry@encana.com	A27
Fischer, Alex		alex.fischer@state.co.us	
Buck, Paul		paul.buck@encana.com	
Arauzo, Steven		steven.arauza@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
468839	SPILL OR RELEASE	AC	10/24/2019		-	A27 12" poly line	EI

General Comment:

On October 21 and October 31, 2019, COGCC Environmental Staff (John Heil and Steven Arauzo) conducted an environmental field inspection of HUNTER RIDGE ENERGY SERVICES LLC (Operator #10442) Spill ID 468839. See attached summary for details.

Location

Lease Road:

Type	Access		
comment:	Operator's truck blocking access to the northern section of the location.		
Corrective Action	Comply with rule 204.	Date:	12/22/2019

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil with a detectable hydrocarbon odor located north of the Water Collection Vault.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.	Date:	12/04/2019

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:					
Corrective Action:					Date:

Paint

Condition	<input style="width: 80%;" type="text"/>
Other (Content)	<input style="width: 80%;" type="text"/>
Other (Capacity)	<input style="width: 80%;" type="text"/>
Other (Type)	<input style="width: 80%;" type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other	Adequate	Walls Insufficient	Base Insufficient	Inadequate
Comment: Secondary containment of the pump generator in disrepair.				
Corrective Action: Install liner material to ensure spill or released materials will be maintained with containment structure.				
Date: 12/22/2019				

Venting:

Yes/No	<input style="width: 80%;" type="text"/>
Comment:	<input style="width: 80%;" type="text"/>

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 468839 Type: SPILL OR API Number: - Status: AC Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699700053	20191021, 31 Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4995734
699700054	20191021, 31 Summary	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4995735