

Location Name: Tindall Operating – Dorothy 1 – Rem #11611
Inspection Date: 11/19/2019



Photo # 1 – View east across location from west side of former vertical separator berm

Location Name: Tindall Operating – Dorothy 1 – Rem #11611
Inspection Date: 11/19/2019



Photo # 2 – View east across former pit excavation



Location Name: Tindall Operating – Dorothy 1 – Rem #11611
Inspection Date: 11/19/2019



11.19.2019

Photo # 3 – View east at east wall of pit excavation, oily soil requires removal



Location Name: Tindall Operating – Dorothy 1 – Rem #11611
Inspection Date: 11/19/2019



Photo # 4 – View north at pit excavation



Location Name: Tindall Operating – Dorothy 1 – Rem #11611
Inspection Date: 11/19/2019



Photo # 5 – Petroleum impacted soil remains in the southwest wall of the pit excavation



Location Name: Tindall Operating – Dorothy 1 – Rem #11611
Inspection Date: 11/19/2019



Photo # 6 – Petroleum impacted soil remains in the southwest wall of the pit excavation

Location Name: Tindall Operating – Dorothy 1 – Rem #11611
Inspection Date: 11/19/2019



Photo # 7 – Petroleum impacted soil remains in the east wall of the pit excavation

Location Name: Tindall Operating – Dorothy 1 – Rem #11611
Inspection Date: 11/19/2019



Photo # 8 – Petroleum impacted soil remains in the east wall of the pit excavation

Location Name: Tindall Operating – Dorothy 1 – Rem #11611
Inspection Date: 11/19/2019



Photo # 9 – Unused equipment and flowline risers need to be removed



Location Name: Tindall Operating – Dorothy 1 – Rem #11611
Inspection Date: 11/19/2019



Photo # 10 – View west from former tank battery area, flowline risers, gravel require removal



Location Name: Tindall Operating – Dorothy 1 – Rem #11611
Inspection Date: 11/19/2019



Photo # 11 – View south at former tank battery area, flowline risers, oily gravel require removal



Location Name: Tindall Operating – Dorothy 1 – Rem #11611
Inspection Date: 11/19/2019



Photo # 12 – View north at cement on plastic



Location Name: Tindall Operating – Dorothy 1 – Rem #11611
Inspection Date: 11/19/2019



Photo # 13 – View north at cement on plastic and soil stockpile



Location Name: Tindall Operating – Dorothy 1 – Rem #11611
Inspection Date: 11/19/2019




Photo # 14 – View east along soil berm south of the location



Location Name: Tindall Operating – Dorothy 1 – Rem #11611
Inspection Date: 11/19/2019



Photo # 15 – View west along soil berm on south side of the location

