

Inspection Photos
Operator: BP America
Location/API #: 067-05796
Date: 11-12-2019



Photo 1. Aerial view of project area (2016 Google Earth). Red “X’s” indicate areas within the project area where erosion and sedimentation is occurring.



Photo 2. View of erosional channels within the western project area (northwestern corner of southern working surface). Channels are approximately 2-3 feet wide, and 6 to 10 inches deep.



Photo 3. View of sediment deposition and wattles filling with sediment, downslope of erosional channels in Photo 2. Sediment flows off of the working area in this corner.



Photo 4. View of cable that remains within the interim reclamation area.



Photo 5. View of musk thistles (approximately 50) individuals observed.



Photo 6. View of area in the northern project area where sediment flows off of the well pad.



Photo 7. View of reference area, comprised of open sagebrush shrubland and grassland mosaic, with scattered pinyon and juniper trees.