

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/20/2019

Submitted Date:

11/22/2019

Document Number:

696101602

FIELD INSPECTION FORMLoc ID 310066 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

13 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		EHSRC@bonanzacrk.com	All Inspections
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295873	WELL	TA	10/15/2014	OW	123-25828	NORTH PLATTE 22-24	TA

General Comment:

This is a WELL inspection.

Well(s): 1: Temporarily Abandoned | TA.

Battery: Inactive | Shut-down.

Centralized Battery serves 4 Location IDs (413629, 310062, 310066, 310069).

(Well(s): 4: Temporarily Abandoned | TA).

Refer to Field Inspection Report doc. #696101600 and/or Location ID #413629 for Battery / Facility, Equipment info.

Location				
Lease Road:				
Type	Access			
comment:	Adequate			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type				
Comment:	Refer to Field Inspection Report doc. #696101600 and/or Location ID #413629 for Battery / Facility, Equipment info.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Sign at access road to wellsite. Well NOT visible from sign. Consider posting an additional sign at wellsite similar to what is at other Bonanza Creek wells. See photos #1, 2.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type				
Comment:	Refer to Field Inspection Report doc. #696101600 and/or Location ID #413629 for Battery / Facility, Equipment info.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Iron panel.			
Corrective Action:				Date:
Equipment:				
Type: Plunger Lift	# 0			corrective date
Comment:				
Corrective Action:				Date:
Type:	#			
Comment:	Refer to Field Inspection Report doc. #696101600 and/or Location ID #413629 for Battery / Facility, Equipment info.			
Corrective Action:				Date:
Type: Other	# 1			

Comment: Wellhead: w/ Master & casing valves.			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment: Appears plumbed to surface.			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.389129,-104.388301
Comment: Centralized Battery serves 4 Location IDs (413629, 310062, 310066, 310069). Refer to Field Inspection Report doc. #696101600 and/or Location ID #413629 for Battery / Facility, Equipment info.					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	295873	Type:	WELL	API Number:	123-25828	Status:	TA	Insp. Status:	TA
Idle Well									
Purpose:		<input type="checkbox"/> Shut In		<input checked="" type="checkbox"/> Temporarily Abandoned		Reminder: EQUIPMENT PRESENT/DISCONNECTED			
Comment:		<div>Temporarily Abandoned TA. Observed well disconnected from flowline. Form 4 doc. #402066822 indicates TA: 08/14/2014. Approved. Form 21 Doc# 401107896 MIT done: 05/24/2016. Approved.</div>							
Corrective Action:							Date:		

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On WED 11/20/2019 at approximately 14:13 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC Location Name: North Platte /22-24 Pad Location ID: 310066 Well Name: North Platte 22-24 API: 05-123-25828 Location County: Weld County, Colorado Weather: Overcast & Dry.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 4 Location IDs (413629, 310062, 310066, 310069). (Well(s): 4: Temporarily Abandoned TA).</p> <p>Refer to Field Inspection Report doc. #696101600 and/or Location ID #413629 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	11/22/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
696101603	Site photos	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4996814