

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/15/2019

Submitted Date:

11/17/2019

Document Number:

679706117

FIELD INSPECTION FORM

Loc ID 430926 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10591

Name of Operator: AUGUSTUS ENERGY PARTNERS II LLC

Address: 2016 GRAND AVENUE SUITE A

City: BILLINGS State: MT Zip: 59102

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 7 Number of Comments
 2 Number of Corrective Actions
☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Zimmerman, Duane	406-860-1432	dzimmerman@augustusenergy.com	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
430928	WELL	PR	12/05/2014	OW	103-11954	Wiley 23-3-97 H1	PR

General Comment:

COGCC Inspection Report Summary.

On 11-15-2019 at approximately 13:45, inspector Rick Moran, conducted a follow up inspection at Augustus Energy Partners well Wiley 23-3-97 H1 in Rio Blanco county of FIR document 679705029.

The following compliance issues were resolved:

- 1) Oily rags in open bucket.
- 2) Stained soil next to separator & tanks.
- 3) Detached well head sign.
- 4) 3 tanks missing labels.
- 5) 3 barrels without labels.
- 6) Missing bird protection on stack west side of 500 bbl tanks.

Additional compliance issues:

- 1) ~100 bbl tank with incomplete label (missing operator name, phone #, capacity), Photo 6. Complete by 1-15-2020.
- 2) Missing bird protection on 1 stack in compressor(?) building. Photo 7. Complete by 1-15-2020.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679706117.

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	~100 bbl tank with incomplete label (missing operator name, phone #, capacity).		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	01/15/2020
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 13		

Comment: Missing bird protection on 1 stack in compressor(?) building.		Date:	
Corrective Action: Install wildlife screen per Rule 605.b.(7).		Date:	01/15/2020
Type: Horizontal Heated Separator	# 2		
Comment:		Date:	
Corrective Action:		Date:	
Type: Ancillary equipment	# 8		
Comment: 2 containers of methanol, 1 container triethylene glycol, 1 container motor oil, 4 Costalguard EG 50.		Date:	
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:		Date:	
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	<100 BBLS	STEEL AST		40.209900,-108.241400
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	500 BBLS	STEEL AST		40.209300,-108.241000
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		Adequate
Comment:				

Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	6	500 BBLs	STEEL AST		40.209300,-108.241000	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	430928	Type:	WELL	API Number:	103-11954	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well.								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Check Dams	Pass			Material Handling And Spill Prevention	Pass	
Retention Ponds	Pass					
Berms	Pass					
Ditches	Pass					

Comment: No apparent significant soil migration, erosion, or soil movement on location.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402241295	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4990479
679706118	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4990476