

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/19/2019

Submitted Date:

11/19/2019

Document Number:

696101584

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
305671 \_\_\_\_\_ Evins, Bret \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: \_\_\_\_\_ 8960 \_\_\_\_\_  
Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY  
Address: 410 17TH STREET SUITE #1400  
City: \_\_\_\_\_ DENVER \_\_\_\_\_ State: \_\_\_\_\_ CO \_\_\_\_\_ Zip: \_\_\_\_\_ 80202 \_\_\_\_\_

**Findings:**

- 13 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
,		EHSRC@bonanzacrk.com	<a href="#">All Inspections</a>
MacLaren, Joe		joe.maclaren@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280955	WELL	PA	07/03/2019	GW	123-23332	LAURA 8-28	PA
447085	TANK BATTERY	AC	07/29/2016		-	LAURA-65N63W 28SENE	IO
447086	TANK BATTERY	AC	07/29/2016		-	LAURA-65N63W 28SENE	IO

**General Comment:**

This is a **PLUGGED & ABANDONED WELL & BATTERY** inspection.  
Well(s): 1: Plugged & Abandoned | PA.  
Battery: Abandoned. Most equipment removed.  
Reclamation progressing.  
  
Abandoned Battery SE corner GPS coordinates: 40.372510, -104.433274.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective ActionL		Date:	

Overall Good:

Emergency Contact Number:	
Comment:	<input style="width: 500px; height: 20px;" type="text"/>
Corrective Action:	<input style="width: 500px; height: 20px;" type="text"/>
Date:	_____

<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment (Gas meter run) at Abandoned Battery site. Refer to Rule 603.f. See photo #2.		
Corrective Action:	Remove unused equipment (Gas meter run) at Abandoned Battery site. Comply w/ Rule 603.f. See photo #2.	Date:	12/20/2019

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 600px; height: 20px;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 0		
Comment:	Abandoned Well & Battery.		
Corrective Action:		Date:	
Type: Emission Control Device	# 0		
Comment:	Abandoned Well & Battery.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Remains at Abandoned Battery site.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 0		
Comment:	Abandoned Well & Battery.		
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:	Remains at Abandoned Battery site.		
Corrective Action:		Date:	

<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS

CRUDE OIL	0				
Comment: <a href="#">Abandoned Well &amp; Battery.</a>					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				
Comment: <a href="#">Abandoned Well &amp; Battery.</a>					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 280955 Type: WELL API Number: 123-23332 Status: PA Insp. Status: PA

**Workover**

Comment: Plugged & Abandoned | PA.  
Casing appears to be cut / capped.  
Form 6 doc. #402100593 indicates cut & cap date: 06/26/2019. Approved.

Corrective Action:

Date:

Facility ID: 447085 Type: TANK API Number: - Status: AC Insp. Status: IO

Facility ID: 447086 Type: TANK API Number: - Status: AC Insp. Status: IO

Reclamation - Storm Water - Pit						
<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				
Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/>						Date: _____
<b>Pits:</b> <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On TUE 11/19/2019 at approximately 16:21 hrs. I, Bret Evins, conducted an on-site inspection at:                      Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC                      Location Name: LAURA-65N63W /28SENE                      Location ID: 305671                      Well Name: Laura 8-28                      API: 05-123-23332                      Location County: Weld County, Colorado                      Weather: Overcast &amp; Dry.</p> <p>While there, I observed:                      Well(s): 1: Plugged &amp; Abandoned   PA.                      Battery: Abandoned. Most equipment removed.                      Reclamation progressing.</p> <p>Abandoned Battery SE corner GPS coordinates: 40.372510, -104.433274.</p> <p>During this inspection the following possible compliance issues were observed:                      1.) Unused equipment (Gas meter run) at Abandoned Battery site.                      Refer to Rule 603.f.                      Remove unused equipment (Gas meter run) at Abandoned Battery site.                      Comply w/ Rule 603.f.                      Corrective Action date: 12/20/2019.                      See photo #2.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	evinsb	11/19/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402243905	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4992815">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4992815</a>
696101585	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4992814">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4992814</a>