

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/19/2019

Submitted Date:

11/19/2019

Document Number:

696101586

**FIELD INSPECTION FORM**Loc ID 331413 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

15 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
MacLaren, Joe		joe.maclaren@state.co.us	
,		dnr_cogccengineering@state.co.us	
,		EHSRC@bonanzacrk.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261886	WELL	TA	02/01/2018	GW	123-20656	DOW 32-28	PA

**General Comment:**

This is a PLUGGED & ABANDONED WELL & BATTERY inspection.  
 Well(s): 1: Plugged & Abandoned | PA.  
 Battery: Abandoned. Most equipment removed.  
 Reclamation progressing.

Abandoned Battery SE corner GPS coordinates: 40.374897, -104.437971.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment. a.) Gas meter runs at Abandoned Battery site. b.) 4: Deadman anchors at Plugged & Abandoned   PA wellsite. Refer to Rule 603.f. See photos #2, 3.		
Corrective Action:	Remove unused equipment. a.) Gas meter runs at Abandoned Battery site. b.) 4: Deadman anchors at Plugged & Abandoned   PA wellsite. Comply w/ Rule 603.f. See photos #2, 3.		Date: <u>12/20/2019</u>
Type	TRASH		
Comment:	Junk (Cut casing pipe, well fence) at Plugged & Abandoned   PA wellsite. Refer to Rule 603.f. See photo #4.		
Corrective Action:	Remove Junk (Cut casing pipe, well fence) at Plugged & Abandoned   PA wellsite. Comply w/ Rule 603.f. See photo #4.		Date: <u>11/27/2019</u>
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Plunger Lift	# 0		corrective date
Comment:	Abandoned Well & Battery.		
Corrective Action:			Date:
Type: Gas Meter Run	# 3		
Comment:	Remains at Abandoned Battery site.		
Corrective Action:			Date:
Type: Emission Control Device	# 0		
Comment:	Abandoned Well & Battery.		

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 0		
Comment:	Abandoned Well & Battery.		
Corrective Action:		Date:	
Type: Pig Station	# 2		
Comment:	Remains at Abandoned Battery site.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	Remains at Abandoned wellsite.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	0				,	
Comment:	Abandoned Well & Battery.					
Corrective Action:					Date:	

**Paint**

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	0				,	
Comment:	Abandoned Well & Battery.					
Corrective Action:				Date:		

**Paint**

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	261886	Type:	WELL	API Number:	123-20656	Status:	TA	Insp. Status:	PA
Workover									
Comment:	Plugged & Abandoned   PA. Casing appears to be cut / capped. Form 6 doc. #402089957 indicates cut & cap date: 06/24/2019. Approval Pending.								
Corrective Action:								Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On TUE 11/19/2019 at approximately 16:28 hrs. I, Bret Evins, conducted an on-site inspection at:  Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC  Location Name: DOW-65N63W /28SWNE  Location ID: 331413  Well Name: DOW 32-28  API: 05-123-20656  Location County: Weld County, Colorado  Weather: Overcast &amp; Dry.</p> <p>While there, I observed:  Well(s): 1: Plugged &amp; Abandoned   PA.  Battery: Abandoned. Most equipment removed.  Reclamation progressing.</p> <p>Abandoned Battery SE corner GPS coordinates: 40.374897, -104.437971.</p> <p>During this inspection the following possible compliance issues were observed:  1.) Unused equipment.  a.) Gas meter runs at Abandoned Battery site.  b.) 4: Deadman anchors at Plugged &amp; Abandoned   PA wellsite.  Refer to Rule 603.f.  Remove unused equipment.  a.) Gas meter runs at Abandoned Battery site.  b.) 4: Deadman anchors at Plugged &amp; Abandoned   PA wellsite.  Comply w/ Rule 603.f.  Corrective Action date: 12/20/2019.  See photos #2, 3.</p> <p>2.) Junk (Cut casing pipe, well fence) at Plugged &amp; Abandoned   PA wellsite.  Refer to Rule 603.f.  Remove Junk (Cut casing pipe, well fence) at Plugged &amp; Abandoned   PA wellsite.  Comply w/ Rule 603.f.  Corrective Action date: 11/27/2019.  See photo #4.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	evinsb	11/19/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402243906	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4992817">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4992817</a>
696101587	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4992816">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4992816</a>