

# Inspection Photos

API: 05-073-06369

Operator: NIGHTHAWK PRODUCTION

Inspection Date: 11/25/2019



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06369 | Date: 11/25/2019

## Inspection Photos



**Photo 1.** Facing east along the access road which was requested to remain. There are erosion issues along the road that need to be repaired and stabilized. Previous corrective action was not performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06369 | Date: 11/25/2019

## Inspection Photos



**Photo 2.** Facing east along the access road which was requested to remain. There are erosion issues along the road that need to be repaired and stabilized. Arrow points to 3.5 ft. shovel to show depth of erosion. Previous corrective action was not performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06369 | Date: 11/25/2019

## Inspection Photos



**Photo 3.** Facing east along the access road closer to the location which was reclaimed and fenced. The fence is degraded and has not been repaired. The photo depicts noncompliance of the corrective action.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06369 | Date: 11/25/2019

## Inspection Photos



**Photo 4.** Wattles are degraded along the reclaimed portion of the access road. Wire from the electric fence is strung along the ground. The photo depicts noncompliance of the corrective action.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06369 | Date: 11/25/2019

## Inspection Photos



**Photo 5.** Facing back to the west at the reclaimed portion of the access road. Arrow points to wattles that are not maintained. The photo depicts noncompliance of the corrective action.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06369 | Date: 11/25/2019

## Inspection Photos



**Photo 6.** Facing east at the location. Perimeter is fenced and in good condition.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06369 | Date: 11/25/2019

## Inspection Photos



**Photo 7.** Facing east at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06369 | Date: 11/25/2019

## Inspection Photos



**Photo 8.** Facing west at the location. Vegetation is well established at this area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06369 | Date: 11/25/2019