

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/26/2019

Submitted Date:

11/26/2019

Document Number:

696300912

**FIELD INSPECTION FORM**Loc ID 422755 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

15 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kraich, Adam		adam.kraich@state.co.us	
,		NBL_DJBU_Inspections@NB LENERGY.COM	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
422766	WELL	PR	05/01/2019	OW	123-33378	Peterson PC LG 19-06	TA

**General Comment:**

This is a Field Inspection. Interim Reclamation Inspections #696200360 dated 7/8/2019, #696200564 dated 8/08/2019, #696200604 dated 8/16/2019, and #696200784 dated 9/23/2019 to document compliance for the following corrective actions:  
1003.f: Noxious weed management are STILL applicable

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	Unmarked riser at wellhead, see photo 2		
Corrective Action:	Comply with Rule 603.f .	Date:	11/29/2019
Type	OTHER		
Comment:	Stained Soil at Wellhead and Gas Engine, see photos 2 and 4		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.	Date:	12/13/2019
Type	UNUSED EQUIPMENT		
Comment:	Unused Chemical drum stains/Containment and tubing, see photo 3		
Corrective Action:	Comply with Rule 603.f .	Date:	12/13/2019
Type	UNUSED EQUIPMENT		
Comment:	Unused Wellhead parts, see Photo 2		
Corrective Action:	Comply with Rule 603.f .	Date:	12/13/2019

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Type	PUMP JACK		
Comment:	Panel		
Corrective Action:		Date:	

**Equipment:**

Type: Bradenhead	# 1		corrective date
Comment:	Appears to be plumbed to Surface		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,	
Comment:						
Corrective Action:					Date:	

**Paint**

Condition	Adequate		
Other (Content)			
Other (Capacity)	24 BBLs		
Other (Type)			

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Comment:		Shares berm with the Crude Oil Tank				Date:	
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	1	500 BBLs	STEEL AST		40.648900,-104.022590		
Comment:						Date:	
Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:						Date:	
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	1	500 BBLs	STEEL AST		,		
Comment:						Date:	
Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Comment:		Shares berm with Crude Oil Tank				Date:	
Corrective Action:						Date:	
<u>Venting:</u>							
Yes/No							
Comment:							
Corrective Action:					Date:		
<u>Flaring:</u>							
Type							
Comment:							
Corrective Action:					Date:		

**Inspected Facilities**Facility ID: 422766 Type: WELL API Number: 123-33378 Status: PR Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: TA

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday 11/21/2019 at approximately 11:49, I, Inspector Erica Petrie, conducted a Field Inspection at Noble Energy INC, Peterson PC LG 19-6, Location ID #422755 in Weld County, Colorado.</p> <p>While there, I observed Production Operations</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Stained Soil at Wellhead and Gas Engine, see photo 2 and 4. Comply with Rule 907.e. Corrective Action date 12.13.2019</p> <p>Unused Chemical Drums Stains/Containment and Tubing at Pumping Unit, see photo 3. Comply with Rule 603.f. Corrective Action date 12.13.2019</p> <p>Unmarked 2" Riser at Wellhead. Refer to Rule 603.f about unmarked Risers. See Photo 2. Comply with Rule 603.f. Corrective Action date 11.29.2019</p> <p>Unused Wellhead parts at Pumping Unit, see photo 2. Comply with Rule 603.f. Corrective Action date 12.13.2019</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report. Continuing Educational Inspections</p>	petrie	11/26/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696300913	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4999091">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4999091</a>