

Inspection Photos

11/25/2019

Operator: WESTERN OPERATING COMPANY -
95620

Location ID: 312291
Logan County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos

Operator Name: WESTERN OPERATING COMPANY - 95620

Location ID: 312291



Photo 1: Photo taken from the east end of the location, facing south. Photo shows stormwater erosion degradation has been allowed to continue on the location.

Inspection Photos

Operator Name: WESTERN OPERATING COMPANY - 95620

Location ID: 312291



Photo 2: Continued from photo 1. Photo facing east. Photo shows stormwater erosion degradation has been allowed to continue on the location. Photo also shows wattles in disrepair and that no additional BMPs to stabilize the soils have been installed per corrective actions and 1002.f.

Inspection Photos

Operator Name: WESTERN OPERATING COMPANY - 95620

Location ID: 312291



Photo 3: See comments under photo 2. 6 foot measuring stick for reference.

Inspection Photos

Operator Name: WESTERN OPERATING COMPANY - 95620

Location ID: 312291



Photo 4: See comments under photo 3.

Inspection Photos

Operator Name: WESTERN OPERATING COMPANY - 95620

Location ID: 312291



Photo 5: Photo taken from the east of the location, facing southeast. Photo shows sediment deposition due to sediment laden stormwater discharge from the location and unstabilized slopes.

Inspection Photos
Operator Name: WESTERN OPERATING COMPANY - 95620
Location ID: 312291



Photo 6: See comments under photo 4.

Inspection Photos
Operator Name: WESTERN OPERATING COMPANY - 95620
Location ID: 312291



Photo 7: Photo taken from the southeast end of the pit, facing west. Photo shows straw wattles in disrepair; Operator failed to install BMP in accordance with good engineering practices.

Inspection Photos

Operator Name: WESTERN OPERATING COMPANY - 95620

Location ID: 312291



Photo 8: Photo taken from the south end of the pit, facing west. Photo shows areas where vegetative establishment is not occurring. Impacted soils likely remain.

Inspection Photos
Operator Name: WESTERN OPERATING COMPANY - 95620
Location ID: 312291



Photo 9: Photo taken from the southwest end of the pit, facing west. Photo shows areas where desirable vegetative establishment is not occurring, and erosion degradation.

Inspection Photos

Operator Name: WESTERN OPERATING COMPANY - 95620

Location ID: 312291



Photo 10: Continued from photo 9.

Inspection Photos

Operator Name: WESTERN OPERATING COMPANY - 95620

Location ID: 312291



Photo 11: Photo taken from the southwest end of the pit, facing southwest. Photo shows erosion degradation and sediment deposition onto the adjacent lands.

Inspection Photos

Operator Name: WESTERN OPERATING COMPANY - 95620

Location ID: 312291



Photo 12: Photo taken from the southwest end of the pit, facing east. Photo shows erosion degradation.

Inspection Photos

Operator Name: WESTERN OPERATING COMPANY - 95620

Location ID: 312291



Photo 13: Photo taken from the southwest end of the pit, facing east. Photo shows erosion degradation and wattles in improper functioning condition.

Inspection Photos

Operator Name: WESTERN OPERATING COMPANY - 95620

Location ID: 312291



Photo 14: Photo taken from the southwest end of the location, facing south. Photo shows areas where desirable vegetative establishment is not occurring, and erosion degradation.

Inspection Photos

Operator Name: WESTERN OPERATING COMPANY - 95620

Location ID: 312291



Photo 15: Photo taken from the west end of the location. Photo shows erosion degradation has not been repaired or stabilized.



Inspection Photos
Operator Name: WESTERN OPERATING COMPANY - 95620
Location ID: 312291



Photo 16: Continued from photo 15.