

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/19/2019

Submitted Date:

11/22/2019

Document Number:

688000344

FIELD INSPECTION FORM

Loc ID 319436 Inspector Name: YOUNG, ROB On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 88380
Name of Operator: TINDALL OPERATING COMPANY
Address: P.O. BOX 4507
City: ENGLEWOOD State: CO Zip: 80155

Findings:

- 6 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Simms, John	(303) 825-8956	dnroilgas@hotmail.com	All Inspections
Witzell, Carrie	303-825-8956	clwitzell@hotmail.com	
Simms, John	303-825-8956	jasimms9@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
111628	PIT	AC			-	DOROTHY 1	EI

General Comment:

Environmental inspection related to Rem #11611. Additional excavation of petroleum impacted soil is required. Gravel/oily gravel removal from former tank battery and vertical separator area is required. Disposal of stockpiled petroleum impacted soil and cement is required.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Well tubing, ASTs and treater have been removed from the location. Risers remain in place at the former treater, AST and meter areas. Wellhead and minor amounts of unused equipment are stockpiled at the former meter location.		
Corrective Action:	Remove all unused surface equipment and flowline/dumpline risers as required by Rule 1004.	Date:	07/06/2019

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 111628 Type: PIT API Number: - Status: AC Insp. Status: EI

Environmental

Waste Management:

Type	Management	Condition	GPS (Lat)	(Long)
Workover	Other	Inadequate		
Comment	Cement from well plugging remains on location			
Corrective Action	Dispose of cement in accordance with Rule 907.f. and provide disposal documentation to COGCC			Date: <u>07/06/2019</u>
Oily Soil	Piles	Inadequate		
Comment	Oily soil has been stockpiled on location, and oily soil remains in pit. Operator has not implemented approved Form 27 for pit closure			
Corrective Action	Handle oily waste from pit and stockpile in accordance with Rule 907.e. and provide disposal documentation on Form 27 Supplemental Report for Remediation #11611			Date: <u>07/06/2019</u>

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 111628 Lat: 40.592969 Long: -103.904781

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date: _____

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment: [Form 27 for pit closure was received and approved on 7/27/2019. Remediation #11611 was assigned. No followup information received. No oily waste has been removed.](#)

Corrective Action

[Provide status update to COGCC with planned timeframe for disposal of oily soil from pit, and planned timing for excavation, confirmation soil sampling and backfill of pit with commencement of final reclamation.](#)

Date: 07/06/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402247034	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4996102
688000345	Location photographs	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4996101