

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/22/2019

Submitted Date:

11/22/2019

Document Number:

689703854

**FIELD INSPECTION FORM**

Loc ID: 335392      Inspector Name: LONGWORTH, MIKE      On-Site Inspection:       2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: PO BOX 370  
City: PARACHUTE      State: CO      Zip: 81635

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 9 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261848	WELL	PR	11/27/2001	GW	045-07985	PA 332-33	PR
274808	WELL	PR	04/04/2005	OW	045-13398	PA 431-33	PR
274809	WELL	PR	04/08/2005	GW	045-13397	PA 432-33	PR

**General Comment:**

COGCC Inspection Report Summary  
On Friday 11/22/2019 at approximately 1445 hrs, I, Inspector Mike Longworth, conducted an inspection at TEP ROCKY MOUNTAIN LLC PA-66S95W 33SWNE, at Location # 335392 in Garfield County, Colorado  
During this inspection the following possible compliance issues were observed:  
Access road into well site not being maintained.  
Repair and maintain lease road to comply with rule 204.  
C.A. Date 12/23/2019  
Sediment washing from around separators into roadside ditch.  
Install or repair required BMPs per Rule 1002.f.  
C.A. Date 12/23/2019  
A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

<b>Location</b>			
<b>Lease Road:</b>			
Type	Access		
comment:	Access road into well site not being maintained.		
Corrective Action:	Repair and maintain lease road to comply with rule 204.	Date:	12/23/2019
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Discoloring of battery sign.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Access road is over grown.		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Dehydrator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	<100 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbl	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:		
Corrective Action:		Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

--	--

Inspected Facilities			
Facility ID: <u>261848</u>	Type: <u>WELL</u>	API Number: <u>045-07985</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:	<u>Producing well</u>		
Corrective Action:		Date:	
Facility ID: <u>274808</u>	Type: <u>WELL</u>	API Number: <u>045-13398</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:	<u>Producing well</u>		
Corrective Action:		Date:	
Facility ID: <u>274809</u>	Type: <u>WELL</u>	API Number: <u>045-13397</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:	<u>Producing well</u>		
Corrective Action:		Date:	

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
		Gravel	Pass			
		Ditches	Pass			
Ditches	Pass					

Comment: [Sediment washing from around separators into roadside ditch.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 12/23/2019

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402247346	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4996817">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4996817</a>
689703855	Inspection 689703854 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4996813">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4996813</a>