

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/14/2019

Submitted Date:

11/22/2019

Document Number:

689803371**FIELD INSPECTION FORM**Loc ID 324673 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 28780Name of Operator: FAHEY OIL & GASAddress: 93 SOUTH COUNTY ROAD 159City: STRASBURG State: CO Zip: 80136**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone        | Email              | Comment        |
|--------------|--------------|--------------------|----------------|
| fahey, dave  | 303-622-9495 | diafahey07@aol.com | owner operator |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 212387      | WELL | PR     | 02/01/2019  | OW         | 057-06280 | STATE 12-1    | SI          |

**General Comment:**

Routine FIU inspection.

**Location**

|                    |   |       |            |
|--------------------|---|-------|------------|
| <b>Lease Road:</b> |   |       |            |
| Type               | Access  |       |            |
| comment:           | Road overgrown and difficult to locate.                 |       |            |
| Corrective Action  | Repair and maintain lease road to comply with rule 204. | Date: | 12/23/2019 |

Overall Good: ☐

|                      |          |       |  |
|----------------------|----------|-------|--|
| <b>Signs/Marker:</b> |          |       |  |
| Type                 | WELLHEAD |       |  |
| Comment:             |          |       |  |
| Corrective Action:   |          | Date: |  |

Emergency Contact Number:

Comment: 303-709-0148

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |                            |       |            |
|--------------------|----------------------------|-------|------------|
| Type               | STORAGE OF SUPL            |       |            |
| Comment:           | Tubing stored at wellhead. |       |            |
| Corrective Action: | Comply with Rule 603.f .   | Date: | 12/23/2019 |

Overall Good: ☐

|                |      |        |  |  |
|----------------|------|--------|--|--|
| <b>Spills:</b> |      |        |  |  |
| Type           | Area | Volume |  |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |           |       |  |
|--------------------|-----------|-------|--|
| <b>Fencing/:</b>   |           |       |  |
| Type               | PUMP JACK |       |  |
| Comment:           |           |       |  |
| Corrective Action: |           | Date: |  |

|                    |   |       |                 |
|--------------------|---|-------|-----------------|
| <b>Equipment:</b>  |   |       | corrective date |
| Type: Pump Jack    | # |       |                 |
| Comment:           |   |       |                 |
| Corrective Action: |   | Date: |                 |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|          |  |  |
|----------|--|--|
| Type     |  |  |
| Comment: |  |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| Corrective Action: |  | Date: |  |
|--------------------|--|-------|--|

| Inspected Facilities   |        |       |      |             |           |         |    |               |    |
|--|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:   | 212387 | Type: | WELL | API Number: | 057-06280 | Status: | PR | Insp. Status: | SI |
| Idle Well  |        |       |      |             |           |         |    |               |    |
| Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned      Reminder: _____ |        |       |      |             |           |         |    |               |    |
| Comment: _____   |        |       |      |             |           |         |    |               |    |
| Corrective Action: _____      Date: _____  |        |       |      |             |           |         |    |               |    |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: [No apparent soil migration; erosion or soil movement.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402247431    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4997018">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4997018</a> |
| 689803372    | Inspection Photos    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4997015">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4997015</a> |