

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/20/2019

Submitted Date:

11/22/2019

Document Number:

696101600**FIELD INSPECTION FORM**Loc ID 413629 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 8960Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANYAddress: 410 17TH STREET SUITE #1400City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**18 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
,		EHSRC@bonanzacrk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412525	WELL	TA	10/16/2014	GW	123-30515	NORTH PLATTE 24A	TA

**General Comment:**

This is a WELL &amp; BATTERY inspection.

Well(s): 1: Temporarily Abandoned | TA.

Battery: Inactive | Shut-down.

Centralized Battery serves 4 Location IDs (413629, 310062, 310066, 310069).

(Well(s): 4: Temporarily Abandoned | TA).

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Adequate			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	BATTERY			
Comment:				
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:	Contents & Capacity NOT posted at what appears to be produced H2O tank. Refer to Rule 210.d. .See photo #4.			
Corrective Action:	Post Contents & Capacity at what appears to be produced H2O tank. Comply w/ Rule 210.d. See photo #4.			Date: 01/21/2020
Type	WELLHEAD			
Comment:	Sign at access road to wellsite. Well NOT visible from sign. Consider posting an additional sign at wellsite similar to what is at other Bonanza Creek wells. See photos #1, 2.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No _____				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	SEPARATOR			
Comment:	Barbed wire. Surrounded by earth berms.			
Corrective Action:				Date:
Type	IGNITOR/COMBUSTOR			
Comment:	Barbed wire.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Iron panel.			
Corrective Action:				Date:
Type	TANK BATTERY			

Comment: <a href="#">Barbed wire.</a>			
Corrective Action:		Date:	

**Equipment:**

Type: Bradenhead	# 1		corrective date
Comment: <a href="#">Appears plumbed to surface.</a>			
Corrective Action:		Date:	
Type: Plunger Lift	# 0		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment: <a href="#">Controls crude oil tanks VOCs. Pilots: OFF   Shut-down.</a>			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment: <a href="#">Wellhead: w/ Master &amp; casing valves.</a>			
Corrective Action:		Date:	
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment: <a href="#">ECD scrubber.</a>			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment: <a href="#">Centralized Battery serves 4 Location IDs (413629, 310062, 310066, 310069).</a>					
Corrective Action:		Date:			

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,
Comment:					
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	Unknown
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Shares berms w/ crude oil tank tanks.				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	300 BBLs	STEEL AST		40.389129,-104.388301
Comment:					
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Shares berms w/ produced H2O tank.				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	412525	Type:	WELL	API Number:	123-30515	Status:	TA	Insp. Status:	TA
Idle Well									
Purpose:		<input type="checkbox"/> Shut In		<input checked="" type="checkbox"/> Temporarily Abandoned		Reminder: EQUIPMENT PRESENT/DISCONNECTED			
Comment:		<div>Temporarily Abandoned   TA. Observed well disconnected from flowline. Form 4 doc. #402066871 indicates TA: 08/08/2014. Approved. Form 21 Doc# 401107902 MIT done: 05/24/2016. Approved.</div>							
Corrective Action:							Date:		

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On WED 11/20/2019 at approximately 14:21 hrs. I, Bret Evins, conducted an on-site inspection at:  Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC  Location Name: NORTH PLATTE /24A  Location ID: 413629  Well Name: North Platte 24A  API: 05-123-30515  Location County: Weld County, Colorado  Weather: Overcast &amp; Dry.</p> <p>While there, I observed:  Well(s): 1: Temporarily Abandoned   TA.  Battery: Inactive   Shut-down.</p> <p>Centralized Battery serves 4 Location IDs (413629, 310062, 310066, 310069).  (Well(s): 4: Temporarily Abandoned   TA).</p> <p>During this inspection the following possible compliance issues were observed:  1.) Contents &amp; Capacity NOT posted at what appears to be produced H2O tank.  Refer to Rule 210.d.  Post Contents &amp; Capacity at what appears to be produced H2O tank.  Comply w/ Rule 210.d.  Corrective Action Date: 01/21/2020  See photo #4.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	evinsb	11/22/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402246628	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4995700">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4995700</a>
696101601	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4995699">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4995699</a>