

Inspection Photos
Location Name: Fitzhugh #6
API: 05-007-05038



Recently constructed secondary containment berm around AST. Drip pan beneath load out valve.



Fitzhugh #7 casing with oil staining.

Inspection Photos
Location Name: Fitzhugh #6
API: 05-007-05038



**Recently constructed addition to land farm treatment area.
Entire treatment area is now fenced.**



**Soil grab samples being collected from existing land farm
treatment cell.**