

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/26/2019

Submitted Date:

11/26/2019

Document Number:

696300912

**FIELD INSPECTION FORM**

Loc ID 422755 Inspector Name: PETRIE, ERICA On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1001 NOBLE ENERGY WAY  
City: HOUSTON State: TX Zip: 77070

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 15 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Kraich, Adam		adam.kraich@state.co.us	
,		NBL_DJBU_Inspections@NB LENERGY.COM	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
422766	WELL	PR	05/01/2019	OW	123-33378	Peterson PC LG 19-06	TA

**General Comment:**

This is a Field Inspection. Interim Reclamation Inspections #696200360 dated 7/8/2019, #696200564 dated 8/08/2019, #696200604 dated 8/16/2019, and #696200784 dated 9/23/2019 to document compliance for the following corrective actions:  
1003.f: Noxious weed management are STILL applicable

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	Unmarked riser at wellhead, see photo 2		
Corrective Action:	Comply with Rule 603.f .	Date:	11/29/2019
Type	OTHER		
Comment:	Stained Soil at Wellhead and Gas Engine, see photos 2 and 4		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.	Date:	12/13/2019
Type	UNUSED EQUIPMENT		
Comment:	Unused Wellhead parts, see Photo 2		
Corrective Action:	Comply with Rule 603.f .	Date:	12/13/2019
Type	UNUSED EQUIPMENT		
Comment:	Unused Chemical drum stains/Containment and tubing, see photo 3		
Corrective Action:	Comply with Rule 603.f .	Date:	12/13/2019

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Type	PUMP JACK		
Comment:	Panel		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to Surface		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	24 BBLS	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Comment: Shares berm with the Crude Oil Tank							
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	1	500 BBLs	STEEL AST		40.648900,-104.022590		
Comment:							
Corrective Action:						Date:	
<b>Paint</b>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<b>Berms</b>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:							
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	1	500 BBLs	STEEL AST		,		
Comment:							
Corrective Action:						Date:	
<b>Paint</b>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<b>Berms</b>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Comment: Shares berm with Crude Oil Tank							
Corrective Action:						Date:	
<b>Venting:</b>							
Yes/No							
Comment:							
Corrective Action:						Date:	
<b>Flaring:</b>							
Type							
Comment:							
Corrective Action:						Date:	

**Inspected Facilities**

Facility ID: 422766 Type: WELL API Number: 123-33378 Status: PR Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary</b>                      On Thursday 11/21/2019 at approximately 11:49, I, Inspector Erica Petrie, conducted a Field Inspection at Noble Energy INC, Peterson PC LG 19-6, Location ID #422755 in Weld County, Colorado.                      While there, I observed Production Operations                      During this inspection the following possible compliance issues were observed:                      Stained Soil at Wellhead and Gas Engine, see photo 2 and 4. Comply with Rule 907.e. Corrective Action date 12.13.2019                      Unused Chemical Drums Stains/Containment and Tubing at Pumping Unit, see photo 3. Comply with Rule 603.f. Corrective Action date 12.13.2019                      Unmarked 2" Riser at Wellhead. Refer to Rule 603.f about unmarked Risers. See Photo 2. Comply with Rule 603.f. Corrective Action date 11.29.2019                      Unused Wellhead parts at Pumping Unit, see photo 2. Comply with Rule 603.f. Corrective Action date 12.13.2019                      A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.                      Continuing Educational Inspections</p>	petrie	11/26/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402249513	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4999094">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4999094</a>
696300913	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4999091">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4999091</a>