

# Inspection Photos

API: 05-073-06398

Operator: KTM OPERATING LLC

Inspection Date: 11/25/2019



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 05-073-06398 | Date: 11/25/2019

## Inspection Photos



**Photo 1.** Facing west along the access road toward the location. There is erosion occurring down the road which is not maintained.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06318 | Date: 11/25/2019

## Inspection Photos



**Photo 2.** Facing northeast toward the location. The perimeter electric fence is in disrepair around the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06318 | Date: 11/25/2019



## Inspection Photos



**Photo 3.** Unused pipe will need to be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06318 | Date: 11/25/2019

## Inspection Photos



**Photo 4.** Electric fence is in disrepair.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06318 | Date: 11/25/2019