

Inspection Photos

API: 05-073-06404

Operator: KTM OPERATING LLC

Inspection Date: 11/25/2019



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06404 | Date: 11/25/2019

Inspection Photos



Photo 1. Facing south at the west side of the location. The perimeter electric fence is in disrepair around the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06404 | Date: 11/25/2019

Inspection Photos



Photo 2. Well sign is posted.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06404 | Date: 11/25/2019

Inspection Photos



Photo 3. Facing north toward the location. Vegetation is progressing in the interim area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06404 | Date: 11/25/2019