

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/03/2019

Submitted Date:

12/04/2019

Document Number:

679706405

**FIELD INSPECTION FORM**

Loc ID 314393 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 16700  
 Name of Operator: CHEVRON USA INC  
 Address: 100 CHEVRON USA INC  
 City: RANGELY State: CO Zip: 81648

**Findings:**

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name    | Phone        | Email                      | Comment |
|-----------------|--------------|----------------------------|---------|
| Sanford, Anita  |              | atlx@chevron.com           |         |
| Kellerby, Shaun | 970-712-1248 | shaun.kellerby@state.co.us |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 228637      | WELL | PR     | 01/01/1999  | OW         | 103-05593 | LEVISON 2     | PR          |

**General Comment:**

[COGCC Inspection Report Summary.](#)

On 12-3-2019 at approximately 16:40, inspector Rick Moran, conducted a routine inspection at Chevron well Levison 2 in Rio Blanco county.

The following compliance issues were observed:  
 1) One and possibly a 2nd fallen deadman marker. Photos 2 & 3. Complete by 1-4-2020.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679706405.

**Location**

Overall Good:

**Signs/Marker:**

|                    |            |       |  |
|--------------------|------------|-------|--|
| Type               | WELLHEAD   |       |  |
| Comment:           |            |       |  |
| Corrective Action: |            | Date: |  |
| Type               | CONTAINERS |       |  |
| Comment:           |            |       |  |
| Corrective Action: |            | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

**Spills:**

| Type | Area | Volume |  |
|------|------|--------|--|
|      |      |        |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

| Type                      |   |       | corrective date |
|---------------------------|---|-------|-----------------|
| Type: Deadman # & Marked  | # 4   |       |                 |
| Comment:                  | One and possibly a 2nd fallen deadman marker.                 |       |                 |
| Corrective Action:        | Install proper guy line markers per Rule 1003.a               | Date: | 01/04/2020      |
| Type: Ancillary equipment | # 1   |       |                 |
| Comment:                  | Container of asphaltene inhibitor with secondary containment. |       |                 |
| Corrective Action:        |   | Date: |                 |
| Type: Submersible Pump    | # 1   |       |                 |
| Comment:                  |   |       |                 |
| Corrective Action:        |   | Date: |                 |

**Venting:**

|                    |  |       |
|--------------------|--|-------|
| Yes/No             |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**

Facility ID: 228637 Type: WELL API Number: 103-05593 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing well on subpump.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs                          | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| Berms            | Pass            |                         |                       | Material Handling And Spill Prevention | Pass                     |         |

Comment: No apparent significant soil migration, erosion, or soil movement on location.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 679706406    | inspection photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5003872">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5003872</a> |