

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/03/2019

Submitted Date:

12/04/2019

Document Number:

679706413

**FIELD INSPECTION FORM**

Loc ID 314250 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 16700  
Name of Operator: CHEVRON USA INC  
Address: 100 CHEVRON USA INC  
City: RANGELY State: CO Zip: 81648

**Findings:**

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Sanford, Anita		atlx@chevron.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228122	WELL	PR	05/19/1998	OW	103-01040	CARNEY C T 8-34	PR

**General Comment:**

[COGCC Inspection Report Summary.](#)

On 12-3-2019 at approximately 17:00, inspector Rick Moran, conducted a routine inspection at Chevron well Carney 8-34 in Rio Blanco county.

The following compliance issues were observed:  
1) 2' wide break in location berm on SW side. Photo 2. Complete by 1-4-2020.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679706413.

**Location**

Overall Good:

**Signs/Marker:**

	Type WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	_____

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

					corrective date
Type: Deadman # & Marked	# 4				
Comment:					
Corrective Action:				Date:	
Type: Submersible Pump	# 1				
Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 228122 Type: WELL API Number: 103-01040 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing well on subpump.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Fail					

Comment: 2' wide break in location berm on SW side,

Corrective Action: Repair or install berms or other secondary containment devices per Rule 605.a.(4).

Date: 01/04/2020

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679706414	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5003876">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5003876</a>