

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/04/2019

Submitted Date:

12/04/2019

Document Number:

697600600

FIELD INSPECTION FORMLoc ID 302551 Inspector Name: GINTAUTAS, PETER On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hamilton, Greg		Gregory.Hamilton@oxy.com	
, Anadarko		COGCCinspections@Anadarko.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
299395	WELL	PR	04/01/2019	GW	123-29347	OLIN STATE L 16-24	EI

General Comment:

Well is in process of abandonment
off-location battery inspected. Battery is shared with other wells
no COGCC facility number assigned to shared battery
battery is about 950 feet to the northeast of well.
REM 14684 associated with location 302551

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: snowy conditions but no spills noted at surface☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 0		
Comment:	plunger lift removed as part of well abandonment as shown in attached photo		
Corrective Action:		Date:	
Type: Bird Protectors	# 3		

Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:	Date:				

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient		Adequate
Comment:	inside same berm system with SE corner at 40.221870, -104.778894 as produced water vaults			
Corrective Action:	Date:			

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	<100 BBLS	CONCRETE SUMP/VAULT		40.221870,-104.778894
Comment:	<p>"correct lat/long" for PW vaults as provided in form 27 (REM 14684) is not at physical location of vaults as seen during inspection</p> <p>REM 14684 correct lat/long provided in initial form 27 was 40.221925, -104.775797 which is at battery for COLAND 33-15 and 9-16, state Olin 4, and HSR State 15-16A wells and not on this location which signs indicate is for Olin State L 16-24.</p> <p>photo with coordinates of SW corner of bermed area attached and sign indicating this is where Olin State L 16-24 PW vault is located</p>				
Corrective Action:	<p>Submit updated form 27 with correct lat long of produced water vault to be removed during REM 14684</p>				
				Date:	12/19/2019

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient		Adequate
Comment:				
Corrective Action:	Date:			

Inspected FacilitiesFacility ID: 299395 Type: WELL API Number: 123-29347 Status: PR Insp. Status: EI**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: well in process of abandonment

Corrective Action: _____

Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697600601	location of well	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5004682
697600602	SW corner of battery for Olin State 16-24	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5004683