

Inspector Name: Moran, Rick

402253532

DIST 4

FORM
INSP

Rev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/04/2019

Submitted Date:

12/04/2019

Document Number:

679706417

FIELD INSPECTION FORM

Loc ID 336553 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: _____

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments
1 Number of Corrective Actions

☒ Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 100 CHEVRON USA INC

City: RANGELY State: CO Zip: 81648

Contact Information:

Contact Name	Phone	Email	Comment
Sanford, Anita		atlx@chevron.com	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229313	WELL	PR	05/01/2019	OW	103-06413	C T CARNEY 20X35	PR

General Comment:

COGCC Inspection Report Summary.

On 12-4-2019 at approximately 9:40, inspector Rick Moran, conducted a routine inspection at in Rio Blanco county.

The following compliance issues were observed:

1) Submit Form 4 with correct well latitude & longitude (40.10321, -108.81072). Currently location on record is the same as well 05-103-05486, Carney 9-35. Complete by 1-4-2020.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679706417.

Corrective Actions
Form 4 - Doc # 402254830 12/5/2019 ATX

LocationOverall Good: ☒**Signs/Marker:**

Type WELLHEAD

Comment:

Corrective Action:

Date:

Emergency Contact Number:

Comment: 911

Corrective Action:

Date:

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Pump Jack

1

corrective date

Comment: Submit Form 4 with correct well latitude & longitude (40.10321, -108.81072). Currently location on record is the same as well 05-103-05486, Carney 9-35.

Corrective Action: Submit reports as per Rule 206.

Date: 01/04/2020

Type: Deadman # & Marked

4

Comment:

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspector Name: Moran, Rick

Inspected Facilities

Facility ID: 229313 Type: WELL API Number: 103-06413 Status: PR Insp. Status: PR

Producing Well

Comment: Pump jack idle at time of inspection.

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					

Comment: No apparent significant soil migration, erosion, or soil movement on location.Corrective Action: Date: Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679706418	inspection photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5003993

Carney 20X35
API: 05-103-06413
Inspection: 679706417



Photo 1. Location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources