

# Inspection Photos

Operator: Enduring Resources  
Location/API #: 067-07758  
Date: 11-14-2019



Photo 1. View of the project area from the southeastern corner facing center.





Photo 2. View of the western fill slope from the southwestern corner facing northward. Revegetation is progressing, largely with grasses such as smooth brome, western wheatgrass, crested wheatgrass, and sand dropseed. Russian olive trees are planted along the western edge of the working area.





Photo 3. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing on fill slopes as described above.





Photo 4. View of the western edge of the working area. Russian olive (*Eleagnus angustifolia*) trees line the edge of the working area. Russian olive is a state and La Plata County-B-List noxious weed species and needs to be removed.





Photo 5. View of erosional rilling at the well pad entrance. BMPs are full of sediment.





Photo 6. View of reference area, comprised of sagebrush and pinyon juniper woodland, with grasses planted in openings.